

TOP SECRET


PRIOGRAY 25X1

Declassification Review by NGA

1967 SEP 2 10 07Z

OUT63007

P 020146Z  
FM NPIC  
TO DIRNSA



OPCEN  
YDHAVQC/CINCEUR  
CINCPACFLT  
FICPAC  
COMNAVFORJAPAN  
AFSCC  
AFSSO AFSC  
AFSSO PACAF  
AFSSO ACIC  
AFSSO FTD  
AFSSO NORTON  
AFSSO ESD  
AFSSO SAMSO  
AFSSO USAFE  
AFSSO TAC  
USAFSS  
INFO FICEUR  
ZEM

TOP SECRET TTTTT [REDACTED] CITE NPIC 1664 25X1  
MISSION 1043 8-22 AUG 67 OAK 01 SEPT 67 PT 03

## PREFACE

THIS IS THE THIRD OF SEVERAL OAK SUPPLEMENT CABLE REPORTS ON  
MISSION 1043 AND PROVIDES INFORMATION ON THE COMIREX TARGETS  
NOT INCLUDED IN THE OAK REPORTS FOR THIS MISSION.

((TEXT WHICH FOLLOWED IDENTICAL TO ABOVE CITED MISSION))

TOP SECRET



OF MESSAGE

25X1

S/C NOTE: ALSO RELAYED [REDACTED]

25X1

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

25X1

TOP SECRET



25X1

MISSION 1043 8-22 AUG 67      OAK      81 SEPT 67      PT 83

PREFACE

THIS IS THE THIRD OF SEVERAL OAK SUPPLEMENT CABLE REPORTS ON MISSION 1043 AND PROVIDES INFORMATION ON THE COMIREX TARGETS NOT INCLUDED IN THE OAK REPORTS FOR THIS MISSION.

THIS REPORT ALSO CONTAINS NON-COMIREX TARGETS REFLECTING SIGNIFICANT CHANGE, TARGETS WITH SIGNIFICANT ORDER OF BATTLE (OOB) INFORMATION, AND TARGETS WHICH ARE NEWLY IDENTIFIED OR KNOWN BUT REPORTED FOR THE FIRST TIME BY NPIC. UPON COMPLETION OF THE MISSION READOUT, ALL TARGETS REPORTED IN THESE CABLES WILL BE CONSOLIDATED BY COMIREX

TARGET CATEGORY AND PUBLISHED.

TARGETS ARE ARRANGED BY SUBJECT AND WITHIN EACH SUBJECT BY COMIREX TARGET NUMBER. PREVIOUSLY REPORTED NON-COMIREX TARGETS ARE LISTED UNDER THE APPROPRIATE SUBJECT AFTER THE LISTING OF COMIREX TARGETS. NEWLY REPORTED TARGETS ARE DESIGNATED AS BONUS TARGETS AND ARE LISTED AFTER THE NON-COMIREX TARGETS. LOCATIONS OF TARGETS IN THIS REPORT ARE INDICATED BY THE COUNTRY CODE AND THE COORDINATES.

SELECTED PHOTOGRAPHIC REFERENCES FOR EACH TARGET FOLLOW THE DESCRIPTION OF THE TARGET. PASS NUMBERS, SUFFIXED WITH A FOR ASCENDING AND D FOR DESCENDING, ARE LISTED FIRST, FOLLOWED BY THE FRAME NUMBERS. SYMBOLS FOR LIMITING CONDITIONS AFFECTING PHOTOGRAPHY ARE C (CLEAR), SC (SCATTERED CLOUD COVER), HC (HEAVY CLOUD COVER), H (HAZEM), CS (CLOUD SHADOW), S (SNOW), O (OBliquity), SD (SEMI-DARKNESS), D (DARKNESS), GC (GROUND COVER), CF (CAMOUFLAGE), GR (GROUND RESOLUTION), AND SS (SMALL SCALE). INTERPRETABILITY OF THE PHOTOGRAPHY IS CATEGORIZED AS G (GOOD), F (FAIR), OR P (POOR). THE EXTENT OF PHOTOGRAPHIC COVERAGE IS DENOTED BY THE SYMBOLS T (TOTAL) OR PT (PARTIAL). THE MODE OF COVERAGE IS INDICATED BY ST (STEREOM), PS (PARTIAL STEREO), OR NS (NONSTEREO).

RECIPIENTS ARE CAUTIONED THAT THE INITIAL SCAN OF PHOTOGRAPHY IS ACCOMPLISHED IN A SHORT TIME AND PRIOR TO FINAL REFINEMENT OF EPHEMERIS DATA. CONSEQUENTLY, FUTURE ANALYSIS MAY RESULT IN ADDITIONAL INFORMATION. MOREOVER, RECIPIENTS ARE CAUTIONED THAT THE IDENTIFICATION OF TARGETS IS BASED PRIMARILY ON PHOTOGRAPHY AND DOES NOT CONSTITUTE A FINISHED INTELLIGENCE JUDGMENT.

HIGHLIGHTS

AT THE MINSK PROBABLE LONG RANGE SAM LAUNCH COMPLEX, USSR, THE CONFIGURATION IS NOW STRONGLY EVIDENT, WITH 3 LAUNCH SITES UNDER CONSTRUCTION AND CLEARINGS IN THE TRACKING/GUIDANCE AREA. PRIOR TO THIS MISSION, ONLY A FENCE LINE AND A PORTION OF THE MAIN ACCESS ROAD WERE APPARENT.

AT THE PERM MUNITIONS - CHEMICAL COMBINE K KIROV 98, USSR, A NEW, PROBABLE DOUBLE-CASE CASTING IS IN THE MID-STAGE OF CONSTRUCTION SOUTHWEST OF THE NITROGLYCERIN PRODUCTION AREA. AT THE KURUMOCH ROCKET ENGINE TEST FACILITY, USSR, A PROBABLE DIFFUSER TUBE HAS BEEN ADDED TO THE WESTERN TEST POSITION OF TEST STAND NO. 3.

1  
OUT63007

STATUS OF TARGET READOUT

THIS SUPPLEMENT REPORTS ON 469 COMIREX TARGETS AND 1 NON-COMIREX TARGET.

MISSILES

PLESETSK MISSILE AND SPACE CENTER UR 6254N 84838E [REDACTED]  
THE ENTIRE MISSILE AND SPACE CENTER IS COVERED WITH THE EXCEPTION OF THE ADMINISTRATION/HOUSING AREA AND LAUNCH SITE 5.

25X1

PLESETSK LAUNCH SITE 1 UR 6255N 84827E [REDACTED]  
SERVICE TOWERS ARE OBSERVED ON BOTH PADS. A VEHICLE/PIECE OF EQUIPMENT IS ON THE RAMP TO THE LEFT PAD. A POSSIBLE VEHICLE/PIECE OF EQUIPMENT IS ON THE RAMP AT THE RIGHT PAD.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

PLESETSK LAUNCH SITE 2 UR 6256N 84831E [REDACTED]  
THE SERVICE TOWER IS OBSERVED IN PLACE AT THE LAUNCH SITE.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

PLESETSK LAUNCH SITE 3 UR 6257N 84841E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

PLESETSK LAUNCH SITE 4 UR 6258N 84846E [REDACTED]  
ERECTOR MECHANISMS ARE OBSERVED IN PLACE AT BOTH PADS.  
A POSSIBLE STRUCTURE HAS BEEN ADDED TO THE SW PORTION OF THE SUPPORT FACILITY AT SITE 4. NO MISSILES OBSERVED.

25X1

25X1

SECTION # 82

PLESETSK LAUNCH SITE 6 UR 6308N 84852E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

PLESETSK LAUNCH SITE 7 UR 6251N 84834E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

PLESETSK LAUNCH SITE 8 UR 6253N 84847E [REDACTED]  
THE 3 LARGE CYLINDRICAL OBJECTS [REDACTED] ARE STILL IN THE SAME POSITION AT THE SS-8 RAIL-TO-ROAD TRANSFER POINT AT SITE 8 AS REPORTED ON [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

25X1

25X1

25X1

PLESETSK LAUNCH SITE 9 UR 6253N 04051E [REDACTED]  
THE GANTRY IS IN PLACE ON THE WEST PAD. MATERIALS FOR  
GANTRY CONSTRUCTION ARE STILL PRESENT TO THE REAR OF  
THE EAST PAD AREA.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

PLESETSK LAUNCH SITE 10 UR 6252N 04052E [REDACTED]  
THE GANTRY IS IN PLACE ON THE EAST PAD. MATERIALS ARE  
PRESENT TO THE REAR OF THE WEST PAD FOR POSSIBLE GANTRY  
CONSTRUCTION.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PLESETSK LAUNCH SITE 11 UR 6257N 04126E [REDACTED]  
A PROBABLE MISSILE TRANSPORTER IS OBSERVED ON THE  
HARDSTAND OF THE NORTH PAD.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PLESETSK PROB LAUNCH SITE 12 UR 6258N 04132E [REDACTED]  
POSSIBLE CONCRETE PAVING EXTENDS FROM THE ACCESS ROAD  
TO THE 2 STRUCTURES/BUILDINGS LOCATED WEST OF THE  
ACCESS ROAD WITHIN THE MAIN SECURED AREA. THE CONCRETE  
PAVING AT THE END OF THE ACCESS ROAD HAS BEEN EXTENDED  
AND WIDENED. A THIRD AREA OF NEW PAVING EXTENDS TO A  
PROBABLE STRUCTURE JUST TO THE EAST OF THE ACCESS ROAD  
AND DIRECTLY EAST OF THE LARGE STRUCTURE/BUILDING ON  
THE WEST SIDE OF THE ACCESS ROAD. NO DEFINITE LAUNCH  
POINT CAN BE IDENTIFIED AT THIS TIME. NO MISSILES OR  
MISSILE-RELATED EQUIPMENT OBSERVED.

25X1  
25X1

PLESETSK LAUNCH SITE 13 UR 6252N 04044E [REDACTED]  
ERECTORS ARE OBSERVED IN PLACE ON BOTH PADS. NO  
MISSILES OBSERVED. SEVERAL VEHICLES/PIECES OF  
EQUIPMENT ARE IN THE VEHICLE PARKING AREA AT THE EAST  
END OF THE LOOP ROAD.  
NO NEW CONSTRUCTION OR CHANGES IN FACILITIES OBSERVED.

25X1  
25X1

PLESETSK LAUNCH SITE 14 UR 6258N 04133E [REDACTED]  
THE PAD AREA HAS BEEN EXTENDED ON THE NORTH SIDE AND  
APPARENTLY LENGTHENED. THE SHAPE OF THE PAD MORE  
NEARLY CONFORMS TO THAT AT LAUNCH SITE 11 THAN  
PREVIOUSLY REPORTED. NO MISSILES OR MISSILE-RELATED  
EQUIPMENT OBSERVED.

25X1  
25X1

PLESETSK LAUNCH SITE 15 UR 6258N 04124E [REDACTED]  
POOR INTERPRETABILITY PRECLUDES A DETAILED READOUT OF  
THIS SITE. IN CONTRAST TO SITE 21, IT APPEARS THAT THE  
LOOP ROAD IS NOT PAVED AT THIS TIME. BACKFILLING OF  
THE SILOS, CONDUIT, AND ASSOCIATED STRUCTURES MAY HAVE  
BEEN COMPLETED AT THE 2 NORTHERN SILOS. NO MISSILES OR  
MISSILE-RELATED EQUIPMENT OBSERVED.

25X1  
25X1

PLESETSK LAUNCH SITE 16 UR 6246N 04035E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

PLESETSK LAUNCH SITE 17 UR 6254N 04124E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY

25X1

SECTION # 83

UNREPORTED FEATURES OBSERVED.

PLESETSK LAUNCH SITE 18 UR 6258N 04139E [REDACTED]  
EARTH-MOUNDING OF SILO HEADWORKS AND ASSOCIATED  
BUILDINGS IS APPARENT. THE ACCESS ROAD APPEARS  
ELEVATED TO THE SILO AREA. NO MISSILES OR  
MISSILE-RELATED EQUIPMENT OBSERVED.

25X1

PLESETSK LAUNCH SITE 19 UR 6255N 04140E [REDACTED]  
SILO HEADWORKS APPEAR COMPLETE. A POSSIBLE STRUCTURE  
IS ATTACHED TO THE EAST SIDE OF THE SILO HEADWORKS. A  
POSSIBLE STRUCTURE IS UNDER CONSTRUCTION ADJACENT TO  
THE SOUTH SIDE OF THE SILO HEADWORKS. A BUILDING UNDER  
CONSTRUCTION ON THE NORTH SIDE OF THE ACCESS ROAD  
APPEARS TO BE IDENTICAL TO ONE AT SITE 17 AND HAS THE  
SAME RELATIONSHIP TO THE SILO HEADWORKS. NO MISSILES  
OR MISSILE-RELATED EQUIPMENT OBSERVED.

25X1

PLESETSK PROB LAUNCH SITE 20 UR 6255N 04140E [REDACTED]  
THE ACCESS ROAD AND PART OF THE PAD AREA APPEAR PAVED.  
A PROBABLE BUILDING IS SOUTH OF THE ACCESS ROAD.  
NO APPARENT MOUNDING OF THE SILO HEADWORKS IS EVIDENT. NO  
MISSILES OR MISSILE-RELATED EQUIPMENT OBSERVED.

25X1

PLESETSK LAUNCH SITE 21 UR 6258N 04123E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

PLESETSK LAUNCH SITE 22 UR 6253N 04145E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

PLESETSK LAUNCH SITE 23 UR 6308N 04133E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY

25X1

UNREPORTED FEATURES OBSERVED.

PLESETSK LAUNCH SITE 24 UR 6388N 84133E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PLESETSK CONSTRUCTION SUPPORT FACILITY UR 6254N 84838E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PLESETSK RAIL-TO-ROAD TRANSFER POINT UR 6255N 84844E [REDACTED]  
SEVERAL RAIL CARS AND SEVERAL POSSIBLE VEHICLES/PIECES  
OF EQUIPMENT ARE IN THE TRANSFER POINT.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

YOSHKAR-OLA ICBM COMPLEX UR 5633N 84881E [REDACTED]  
ALL 6 SITES ARE INTERPRETABLE. NO SIGNIFICANT ACTIVITY  
OBSERVED. THE COMPLEX SUPPORT FACILITY AND THE  
RAIL-TO-ROAD TRANSFER POINT ARE COVERED.

25X1

KOSTROMA ICBM COMPLEX UR 5746N 84181F [REDACTED]  
THE COMPLEX SUPPORT FACILITY CAN BE IDENTIFIED ONLY.  
LAUNCH SITE 37 IS INTERPRETABLE AND REMAINS IN THE

25X1

SECTION # 84

MID-STAGE OF CONSTRUCTION. NO OTHER SIGNIFICANT  
ACTIVITY OBSERVED.

25X1

TEYKOVO ICBM COMPLEX UR 5652N 84034E [REDACTED]  
THE COMPLEX SUPPORT FACILITY, THE RAIL-TO-ROAD TRANSFER  
POINT, AND SITES 3, 4, 5, AND 6 ARE INTERPRETABLE. NO  
SIGNIFICANT ACTIVITY OBSERVED.

25X1

25X1

25X1

TYUMEN ICBM COMPLEX UR 5652N 86551E [REDACTED]  
SITES 2 AND 3 AND THE COMPLEX SUPPORT FACILITY ARE  
INTERPRETABLE. NO SIGNIFICANT ACTIVITY OBSERVED. THE  
RAIL-TO-ROAD TRANSFER POINT CAN BE IDENTIFIED ONLY.

25X1

25X1

NOVOSIBIRSK ICBM COMPLEX UR 5515N 88259E [REDACTED]  
THE 5 KNOWN SS-7 LAUNCH SITES, THE COMPLEX SUPPORT  
FACILITY, AND THE RAIL-TO-ROAD TRANSFER POINT ARE  
OBSERVED ON PHOTOGRAPHY OF FAIR-TO-POOR  
INTERPRETABILITY. NO SIGNIFICANT ACTIVITY IS OBSERVED  
AT THE LAUNCH SITES OR THE RAIL-TO-ROAD TRANSFER POINT.  
THE COMPLEX SUPPORT FACILITY APPEARS TO BE AT A NORMAL  
LEVEL OF ACTIVITY.

25X1

25X1

25X1

25X1

25X1

25X1

25X1

25X1

25X1

ALEYSK ICBM COMPLEX UR 5229N 08243E [REDACTED]  
EIGHT OF THE 19 KNOWN SITES ARE INTERPRETABLE.  
LAUNCH GROUP B -- SITES 8-11 AND 13 NOW APPEAR  
COMPLETE.  
LAUNCH GROUP C -- SITES 17, 19, AND 20 ARE IN THE  
MID-STAGE OF CONSTRUCTION. NO SIGNIFICANT ACTIVITY  
OBSERVED.

25X1

25X1

25X1

SECTION # 85

TATISHCHEVO ICBM COMPLEX UR 5148N 04534E [REDACTED]  
ONE HUNDRED AND NINETEEN TYPE IID LAUNCH SITES, 1  
POSSIBLE LAUNCH SITE, THE RAIL-TO-ROAD TRANSFER POINT,  
AND THE COMPLEX SUPPORT FACILITY ARE OBSERVED. LAUNCH  
SITES 146, 147, AND 148, PROBABLE LAUNCH SITES 149,  
150, AND 151, AND POSSIBLE LAUNCH SITE 152 ARE FIRST  
OBSERVED ON THIS MISSION QSEE [REDACTED] THE OAK  
REPORT FOR 1843-1a. LAUNCH SITE 146 IS THE CONTROL  
SITE FOR THE L GROUP WITH SILO CORING AND EXCAVATION  
FOR GROUP CONTROL BUILDINGS IN PROGRESS. ALL SITES IN  
THE L GROUP ARE IN EARLY STAGES OF CONSTRUCTION. IN  
THE H GROUP, THERE IS A DEFINITE CONSTRUCTION LAG ON  
SITES 181 AND 126-129 WHICH ARE IN THE MID-STAGE OF  
CONSTRUCTION. THE REMAINING 5 SITES IN THE H GROUP ARE  
WELL INTO THE LATE STAGE OF CONSTRUCTION. CONTROL SITE  
120 IN THE L GROUP HAS THE FOLLOWING PATTERN

25X1

25X1

25X1

124 IN THE K GROUP HAS THE RECTANGULAR MOUND PATTERN OFF-SET APPROXIMATELY A PATTERN WIDTH WEST OF THE SILO. THIS IS THE ONLY SITE THAT APPEARS TO BE ALTERED FROM THE NORMAL PATTERN THAT SURROUNDS THE SILO. THE OFF-SET IS POSSIBLY DUE TO TERRAIN FEATURES. COMPLEX PERIMETER SITES IN THE G, I, J, AND K GROUPS HAVE HELICOPTER PADS INSTALLED. THE 7 HOUND HELICOPTERS AT THE RAIL-TO-ROAD TRANSFER POINT, REPORTED ON MISSION [REDACTED] PROBABLY ARE OR WILL BE PERMANENTLY BASED AT THE COMPLEX. POSSIBLE LAUNCH SITE 145 IS NOT CONSIDERED A VALID SITE AND IS DELETED FROM NPIC LISTINGS. AT THE RAIL-TO-ROAD TRANSFER POINT, RAIL AND VEHICLE ACTIVITY IS HEAVY. A NEW AREA UNDER CONSTRUCTION SOUTH OF THE TRANSFER POINT HAS EXPANDED WITH ADDITIONAL DITCHING AND EARTH GRADING, PROBABLY FOR ADDITIONAL BUILDINGS. FUNCTION OF THIS AREA CANNOT BE DETERMINED, BUT THE AREA IS AN EXPANDED PART OF THE RAIL-TO-ROAD TRANSFER POINT AND IS BEING CONNECTED WITH UTILITIES FROM TRANSFER POINT RESOURCES. THE COMPLEX HARDENED COMMAND AND CONTROL BUILDING HAS BEEN EARTH COVERED AND HOUSING CONSTRUCTION AT THE COMPLEX SUPPORT FACILITY IS COMPLETE. AN AIR LIQUEFACTION PLANT SOUTH OF PETROVSK, ON THE EAST SIDE OF THE COMPLEX MAIN ROAD BETWEEN SITES 91 AND 116, IS COMPLETE. ADJACENT TO THE COMPLETED PLANT, A PROBABLE DUPLICATE FACILITY IS UNDER CONSTRUCTION. THIS PLANT WILL PROBABLY FURNISH THE LIQUID NITROGEN REQUIREMENTS OF THE ICBM COMPLEX. NO OTHER SIGNIFICANT MISSILE ACTIVITY OBSERVED.

DETAILED DATA AND CONSTRUCTION STATUS --

GROUP A -- ALL 18 COMPLETED LAUNCH SITES 01-3 AND 5-11<sup>h</sup> ARE INTERPRETABLE.

GROUP B -- ALL 18 COMPLETED LAUNCH SITES 012-17, 19, 21, 29, AND 30<sup>h</sup> ARE INTERPRETABLE.

GROUP C -- ALL 18 COMPLETED LAUNCH SITES 020, 22, 24-28, 32, 44, AND 57<sup>h</sup> ARE INTERPRETABLE.

GROUP D -- ALL 18 COMPLETED LAUNCH SITES 036-42, 54, 72, AND 73<sup>h</sup> ARE INTERPRETABLE.

GROUP E -- ALL 18 LAUNCH SITES 045, 47, 76, 77, 88, 82, 188, 183, 128, AND 122<sup>h</sup> ARE INTERPRETABLE AND THE GROUP IS NOW COMPLETE.

GROUP F -- ALL 18 COMPLETED LAUNCH SITES 051, 58, 59, 61-63, 65, 66, 89, AND 98<sup>h</sup> ARE INTERPRETABLE.

GROUP G -- ALL 18 COMPLETED LAUNCH SITES 067, 71, 75, 88, 92, 97, 98, 108, 131, AND 137<sup>h</sup> ARE INTERPRETABLE. SITE 92 AND POSSIBLY 88 AND 131 HAVE HELICOPTER PADS.

GROUP H -- ALL 18 LAUNCH SITES ARE INTERPRETABLE. SITES 94-96 AND 102 ARE IN LATE STAGES OF CONSTRUCTION AND SITES 101, 119, AND 126-129 REMAIN IN THE MID-STAGE OF CONSTRUCTION.

GROUP I -- ALL 18 COMPLETED LAUNCH SITES 074, 83-86, 93, 184, 116, AND 136<sup>h</sup> ARE INTERPRETABLE. ALL SITES

25X1

HAVE HELICOPTER PADS.  
GROUP J -- ALL 10 LAUNCH SITES ARE INTERPRETABLE.  
SITES 81, 109-112, 115, 117, 118, AND 123 ARE COMPLETE  
AND HAVE HELICOPTER PADS. SITE 99 REMAINS IN A LATE  
STAGE OF CONSTRUCTION.  
GROUP K -- ALL 10 LAUNCH SITES ARE INTERPRETABLE. ALL  
SITES 121, 124, 125, 132-134, AND 138-141<sup>W</sup> ARE  
COMPLETE AND HAVE HELICOPTER PADS.  
GROUP L -- ALL 9 LAUNCH SITES @143, 144, 146-148,  
PROBABLE 149 THROUGH PROBABLE 151 AND POSSIBLE 152<sup>W</sup> ARE  
INTERPRETABLE. ALL SITES ARE IN EARLY STAGES OF  
CONSTRUCTION. SITE 146 IS THE CONTROL SITE FOR THE

SECTION # 86

GROUP.  
RAIL-TO-ROAD TRANSFER POINT -- COMPLETED LAUNCH SITE  
35X 15 INTERPRETABLE

25X1

**Page Denied**

Next 3 Page(s) In Document Denied

PETROVSKY IRBM LAUNCH SITE UR 5800N 05657E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1 [REDACTED]

SOFIYE-ALEKSEYEVSKOYE MRBM LAUNCH SITE UR 4415N 13122E [REDACTED]  
A POSSIBLE MISSILE ERECTOR IS VISIBLE ON 1 LAUNCH PAD.  
TWO POSSIBLE VEHICLES ARE IN THE MOTOR POOL AREA.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1 [REDACTED]

25X1 [REDACTED]

BARANO-ORENBURGSKOYE MRBM LAUNCH SITE UR 4420N 13130E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1 [REDACTED]

25X1 [REDACTED]

SOFIYE-ALEKSEYEVSKOYE FIXED FLD MRBM SITE UR 4411N 13124E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1 [REDACTED]

25X1 [REDACTED]

BREST MRBM LAUNCH SITE 1 UR 5148N 02400E [REDACTED]  
PROBABLE ERECTORS ARE ON ALL 4 PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1 [REDACTED]

25X1 [REDACTED]

BREST MRBM LAUNCH SITE 2 UR 5151N 02401E [REDACTED]  
PROBABLE ERECTORS ARE ON ALL 4 PADS.

25X1 [REDACTED]

25X1 [REDACTED]

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PISSHCHA FIXED FIELD MRBM SITE UR 5135N 02346E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

ZAMSHANY FIXED FIELD MRBM SITE UR 5151N 02402E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

DYATLOVO MRBM LAUNCH SITE UR 5332N 02517E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

BEREZOVKA MRBM LAUNCH SITE UR 5335N 02527E [REDACTED]  
PROBABLE ERECTORS ARE POSITIONED ON EACH LAUNCH PAD.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

ZBLYANY MRBM LAUNCH SITE UR 5335N 02517E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

BEREZOVKA FIXED FIELD MRBM SITE UR 5342N 02530E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

GRESK MRBM LAUNCH SITE 1 UR 5314N 02742E [REDACTED]  
ON [REDACTED] PROBABLE ERECTORS ARE POSITIONED ON EACH  
LAUNCH PAD.  
[REDACTED] ERECTORS ARE PROBABLY PRESENT ON AT LEAST  
2 LAUNCH PADS.

25X1  
25X1

#### SECTION # 18

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

GRESK MRBM LAUNCH SITE 2 UR 5316N 02740E [REDACTED]  
ON [REDACTED] ONLY THE SUPPORT AREA IS VISIBLE.  
ON [REDACTED] ERECTORS ARE PROBABLY PRESENT ON AT LEAST  
2 OF THE LAUNCH PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

URECHYE MRBM LAUNCH SITE UR 5311N 02758E [REDACTED]  
ON [REDACTED] ONLY 1 LAUNCH PAD AND PART OF THE SUPPORT  
AREA ARE VISIBLE. A PROBABLE ERECTOR IS POSITIONED ON  
THE LAUNCH PAD.  
ON [REDACTED] A POSSIBLE MISSILE ERECTOR IS ON AT LEAST  
1 LAUNCH PAD.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1  
25X1

25X1

JONAVA MRBM LAUNCH SITE UR 5508N 02414E [REDACTED]  
ONLY THE SUPPORT AREA IS VISIBLE.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

25X1

KAISIADORYS FIXED FIELD MRBM SITE UR 5459N 02428E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

25X1

SUDARGAS FIXED FIELD MRBM SITE UR 5508N 02235E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

25X1

LIDA MRBM LAUNCH SITE 2 UR 5357N 02527E [REDACTED]  
A POSSIBLE ERECTOR IS ON 1 PAD.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

SHATSK FIXED FIELD MRBM SITE 1 UR 5327N 02748E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

25X1

KURDZHIPSKAYA MRBM LAUNCH SITE UR 4431N 04088E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

25X1

SHIRVANSKAYA MRBM LAUNCH SITE UR 4425N 03953E [REDACTED]  
ONLY THE LAUNCH POSITIONS ARE VISIBLE.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW

25X1

CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

TULSKAYA FIXED FIELD MRBM SITE UR 4431N 04814E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

MAYKOP FIXED FIELD MRBM SITE UR 4433N 03957E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

MOLOSKOVITSY MRBM LAUNCH SITE 1 UR 5928N 02905E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

MOLOSKOVITSY MRBM LAUNCH SITE 2 UR 5929N 02912E [REDACTED]

25X1  
25X1

#### SECTION # 11

PROBABLE ERECTORS ARE POSITIONED ON 3 PADS. SEVERAL PIECES OF EQUIPMENT ARE VISIBLE ON THE SOUTHERNMOST LAUNCH PAD. NO MISSILES OBSERVED.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

GURLEVO MRBM LAUNCH SITE UR 5925N 02854E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

IVANOVY MRBM LAUNCH SITE UR 5210N 02541E [REDACTED]  
ERECTORS ARE VISIBLE ON ALL 4 PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

MOTOL MRBM LAUNCH SITE UR 5212N 02544E [REDACTED]  
POSSIBLE ERECTORS ARE VISIBLE ON ALL 4 PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

POLOTSK MRBM LAUNCH SITE 1 UR 5522N 02844E [REDACTED]  
A POSSIBLE MISSILE ERECTOR IS OBSERVED ON EACH LAUNCH PAD. PROBABLE PROPELLANT TRAILERS ARE PARKED IN THE PROPELLANT HANDLING AREA.

25X1  
25X1

POLOTSK MRBM LAUNCH SITE 2 UR 5524N 02833E [REDACTED]  
A POSSIBLE MISSILE ERECTOR IS OBSERVED ON EACH OF THE

25X1  
25X1

VISIBLE LAUNCH PADS

PLISSA FIXED FIELD MRBM SITE 1 UR 5512N 02802E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PLISSA FIXED FIELD MRBM SITE 2 UR 5511N 02754E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

POSTAVY MRBM LAUNCH SITE 1 UR 5509N 02653E [ ]  
A PROBABLE MISSILE ERECTOR IS ON EACH LAUNCH PAD.  
PROBABLE PROPELLANT TRAILERS ARE VISIBLE IN THE  
PROPELLANT HANDLING AREA.

25X1  
25X1

KOZYANY MRBM LAUNCH SITE UR 5520N 02651E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

POSTAVY MRBM LAUNCH SITE 2 UR 5506N 02700E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PRUZHANY MRBM LAUNCH SITE 1 UR 5238N 02400E [ ]  
PROBABLE ERECTORS ARE PRESENT ON ALL 4 PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PRUZHANY MRBM LAUNCH SITE 2 UR 5233N 02406E [ ]  
PROBABLE ERECTORS ARE PRESENT ON ALL 4 PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

STRIGOVY FIXED FIELD MRBM SITE UR 5223N 02414E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

SHCHERCHEVO FIXED FIELD MRBM SITE UR 5222N 02410E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

25X1

PRUZHANY FIXED FIELD MRBM SITE UR 5226N 02419E [ ]

SECTION # 12

NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

SHCHITNO FIXED FIELD MRBM SITE 1 UR 5263N 02458E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

BYTEN MRBM LAUNCH SITE 1 UR 5252N 02521E [ ]  
ERECTORS ARE PRESENT ON ALL 4 LAUNCH PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

BYTEN MRBM LAUNCH SITE 2 UR 5255N 02521E [ ]  
ERECTORS ARE PRESENT ON ALL 4 PADS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

BYTEN FIXED FIELD MRBM SITE UR 5254N 02522E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

GAVINOVICHI FIXED FIELD MRBM SITE UR 5381N 02536E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

SMORGON IRBM LAUNCH SITE 2 UR 5426N 02618E [ ]  
A POSSIBLE MISSILE ERECTOR IS VISIBLE ON EACH LAUNCH PAD.

25X1

25X1

SKAUDVILE FIXED FIELD MRBM SITE UR 5523N 02231E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

UKMGERE MRBM LAUNCH SITE UR 5511N 02442E [ ]  
A PROBABLE ERECTOR IS POSITIONED ON EACH LAUNCH PAD.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

BALNINKAI FIXED FIELD MRBM SITE UR 5513N 02501E [ ]

25X1

25X1

NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

VSELYUB MRBM LAUNCH SITE 1 UR 5345N 02542E [REDACTED]  
POSSIBLE MISSILE ERECTORS ARE ON EACH LAUNCH PAD.  
POSSIBLE PROPELLANT TRAILERS ARE IN THE PROPELLANT HANDLING AREA.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

VSELYUB MRBM LAUNCH SITE 2 UR 5347N 02546E [REDACTED]  
POSSIBLE MISSILE ERECTORS ARE ON AT LEAST 2 OF THE 4 LAUNCH PADS. POSSIBLE PROPELLANT TRAILERS ARE IN THE PROPELLANT HANDLING AREA.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

KAPUSTIN YAR/VLADIMIROVKA MSL TEST CTR UR 4835N 04545E [REDACTED]  
ONLY THE EASTERN HALF OF THE SEARCH AREA IS COVERED ON PHOTOGRAPHY WITH APPROXIMATELY 85 PERCENT CLOUD COVER.  
NO NEW MISSILE FACILITIES OBSERVED IN CLOUD-FREE PORTIONS.

KAPUSTIN YAR LAUNCH COMPLEX B UR 4841N 04616E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

KAPUSTIN YAR LAUNCH COMPLEX C UR 4836N 04616E [REDACTED]  
AT LAUNCH AREA 6C, THE CONTROL BUNKERS AND THE OPEN CONDUIT TRENCHES APPEAR TO HAVE BEEN EARTH COVERED. NO MISSILES OBSERVED.  
LAUNCH AREAS 1-5C CAN BE IDENTIFIED ONLY.

SECTION # 13

SARY-SHAGAN LAUNCH COMPLEX C UR 4549N 07325E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

SARY-SHAGAN PROB LR SAM LAUNCH CPLX 1 UR 4685N 07327E [REDACTED]

25X1  
25X1

ON [REDACTED] ALL LAUNCH POSITIONS OF SITES A, B, AND C ARE OCCUPIED BY LAUNCHERS. THE DOLLIES AT SITE A, REPORTED ON [REDACTED] ARE LOCATED IN THE SAME POSITION NEAR THE CENTER OF THE LAUNCH SITE. AN UNIDENTIFIED OBJECT (VEHICLE/PIECE OF EQUIPMENT), WHICH APPEARS TO BE LARGER THAN A DOLLY IS ON THE ROAD NEAR LAUNCH POSITION A/5. NO RAILS ARE IN PLACE AT SITE A. AT LAUNCH POSITION C/2, ONE OF THE DOLLIES APPEARS TO BE POSITIONED AT THE APEX OF THE TRACKS. THE LAUNCHER APPEARS LARGER THAN AT THE OTHER LAUNCH POSITIONS AND IS PROBABLY OCCUPIED. ALL OTHER DOLLIES AT LAUNCH SITES B AND C ARE AT THE HOLD POSITION. CONSTRUCTION CONTINUES IN THE SUPPORT AREA. MOST OF THE TRENCHING IN THIS AREA HAS BEEN BACKFILLED. NO SIGNIFICANT CHANGE IS APPARENT IN THE TRACKING/GUIDANCE RADAR FACILITY. ALL 3 RADAR MOUNDS ARE OCCUPIED. THE BACK NET/SIDE NET AIR WARNING FACILITY AND THE 2 UNIDENTIFIED ASSOCIATED FACILITIES REMAIN UNCHANGED. THE PROBABLE MISSILE-HANDLING FACILITY 10 NM WNW OF THE LAUNCH COMPLEX IS UNCHANGED.

[REDACTED] FACILITIES CAN BE IDENTIFIED ONLY. ON PASS [REDACTED] NO DISCERNIBLE CHANGES ARE OBSERVED EXCEPT THAT BOTH DOLLIES AT LAUNCH POSITION C/2 ARE AT THE HOLD POSITION.

SARY-SHAGAN MRBM IMPACT AREA 1 UR 4617N 87200E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

SARY-SHAGAN MRBM IMPACT AREA 2 UR 4634N 87236E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

SARY-SHAGAN MRBM IMPACT AREA 3 UR 4627N 87244E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

SARY-SHAGAN MRBM IMPACT AREA 4 UR 4628N 87319E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

SARY-SHAGAN MRBM IMPACT AREA 5 UR 4608N 87240E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

25X1

25X1  
25X1

25X1

25X1

25X1

25X1

25X1

25X1

25X1

25X1

25X1

25X1

SASYKTAU MISSILE LAUNCH FACILITY UR 4732N 84926E [REDACTED]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

SARY-SHAGAN IMPACT AREA UR 4623N 87324E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

SARY-SHAGAN AMM IMPACT AREA 1 UR 4715N 87108E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

SARY-SHAGAN AMM IMPACT AREA 3 UR 4655N 87245E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION OF MISSILE IMPACT CRATERS.

SECTION # 14

CRATERS.

NENOKSA MISSILE TEST CENTER UR 6438N 83911E [REDACTED]  
LAUNCH AREAS A, B, AND C AND THE SUPPORT AREA ARE OBSERVED. AT LAUNCH AREA A, THE 3 PREVIOUSLY IDENTIFIED LAUNCHERS ARE STILL PRESENT. AT LAUNCH AREA B, DETAILED ACTIVITY CANNOT BE DETERMINED, BUT THE BOOM CRANE PREVIOUSLY PARKED ON THE CONCRETE LAUNCH PAD IS NOW PROBABLY IN THE PARKING AREA JUST SOUTH OF THE LAUNCH AREA. LAUNCH AREA C CAN BE IDENTIFIED ONLY. NO CHANGES OBSERVED IN THE SUPPORT AREA.

NENOKSA MISSILE TEST CENTER U/I AREA UR 6438N 83913E [REDACTED]  
THIS UNIDENTIFIED ACTIVITY WAS DESIGNATED LAUNCH AREA C ON [REDACTED] AND IS REPORTED UNDER THE NENOKSA MISSILE TEST CENTER.

KURUMOCH ROCKET ENGINE TEST FACILITY UR 5332N 84951E [REDACTED]  
SIGNS OF PREVIOUS TEST ACTIVITY REMAIN AT VERTICAL TEST STANDS 1, 2, AND 3. A PROBABLE DIFFUSER TUBE HAS BEEN ADDED TO THE WESTERN TEST POSITION OF VERTICAL TEST STAND 3. NO MISSILES OR MISSILE-RELATED EQUIPMENT OBSERVED.

UNREPORTED FEATURES OBSERVED

PERM ARMAMENT PLANT 172 UR 5802N 05618E [REDACTED]  
NO LARGE RAIL CARS OBSERVED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1  
25X1

KUYBYSHEV AIRFRAME PLANT STALIN 1 UR 5313N 05817E [REDACTED]  
THE PREVIOUSLY REPORTED NEW BUILDING IS ESSENTIALLY  
COMPLETE. TEN TO 15 LARGE RAIL CARS ARE IN THE PLANT  
AREA. NO OTHER CHANGES OBSERVED. NO MISSILES OR  
MISSILE COMPONENTS OBSERVED.

25X1

UFA AIRCRAFT ENGINE PLANT A-26 UR 5447N 05687E [REDACTED]  
A LARGE NEWLY IDENTIFIED ASSEMBLY-TYPE BUILDING IS  
VISIBLE IN THE SW PORTION OF THE PLANT. THE BUILDING  
IS APPROXIMATELY 40 PERCENT COMPLETE. NO OTHER  
CONSTRUCTION OBSERVED. NO MISSILES, MISSILE  
COMPONENTS, OR LARGE RAIL CARS DISCERNIBLE.

25X1

UFA AIRCRAFT ENGINE PLANT B-26 UR 5447N 05684F [REDACTED]  
NO LARGE RAIL CARS OBSERVED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

KAZAN AIRCRAFT ENGINE PLANT 16 UR 5551N 04986F [REDACTED]  
KAZAN POSSIBLE STATIC TEST FACILITY WAS IDENTIFIED ON  
NO NEW CONSTRUCTION OR CHANGES IN FACILITIES OBSERVED.

25X1

PERM ROCKET ENGINE TEST FACILITY UR 5808N 05634E [REDACTED]  
NO INDICATIONS OF TEST ACTIVITY ARE DISCERNIBLE.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

KUYBYSHEV EXPMT AC ENG PLT KR GLINKA 2 UR 5321N 05013E [REDACTED]  
THE PLANT IS NOT RAIL SERVED. CONSTRUCTION CONTINUES  
IN THE PREVIOUSLY REPORTED AREAS. NO MISSILES OR  
MISSILE COMPONENTS OBSERVED.

25X1

25X1

25X1

SECTION # 15

KUYBYSHEV AIRCRAFT ENGINE PLT FRUNZE 24 UR 5311N 05016E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED

25X1

STERLIYAMAK ROCKET MOTOR TEST FACILITY UR 5341N 05550E [REDACTED]  
THE PREVIOUSLY REPORTED TEST CELL UNDER CONSTRUCTION  
APPEARS TO BE IN MID-TO-LATE STAGES OF CONSTRUCTION.  
NO MISSILES OR MISSILE-RELATED EQUIPMENT OBSERVED. NO  
INDICATIONS OF TEST ACTIVITY ARE APPARENT.

25X1

UFA ROCKET ENGINE TEST FACILITY UR 5458N 05604E [REDACTED]  
NO NEW EVIDENCE OF TEST ACTIVITY OBSERVED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

PERM AIRCRAFT ENGINE PLANT STALIN 19 UR 5759N 05615E [REDACTED]  
NO LARGE RAIL CARS OBSERVED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

PERM ROCKET MOTOR TEST FACILITY UR 5758N 05549E [REDACTED]  
NO INDICATION OF RECENT TEST ACTIVITY OBSERVED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

ZELENOGORSK STATIC TEST FACILITY UR 6813N 02943E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

PRIMORSK ROCKET ENGINE TEST FACILITY UR 6818N 02851E [REDACTED]  
NO INDICATIONS OF TEST ACTIVITY OBSERVED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

LENINGRAD SOLID MOTOR TEST FAC 2 UR 6812N 03042E [REDACTED]  
THREE LIGHT-TONED BLAST MARKS INDICATE A CONTINUING  
HIGH DEGREE OF TEST ACTIVITY.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

LENINGRAD SOLID MOTOR TEST FACILITY 1 UR 6803N 03036E [REDACTED]

25X1

LIGHT-TONED BLAST MARKS, PROBABLY FROM PREVIOUS TEST ACTIVITY, REMAIN.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

LENINGRAD SOLID MOTOR TEST FACILITY 3 UR 6815N 83844E [REDACTED]  
NO APPARENT SIGNS OF RECENT TEST ACTIVITY ARE OBSERVED.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

PAVLOGRAD PROBABLE TEST RANGE UR 4829N 03556E [REDACTED]  
TWO NEW BUILDINGS ARE APPARENT IN THE RANGE SUPPORT/STORAGE AREA. THE SECURED AREA HAS BEEN ENLARGED TO INCLUDE THE NEW BUILDINGS. NEW SECURITY FENCING HAS BEEN ADDED WHICH DOUBLES THE SECURED AREA AT THE DRIVE-IN TEST POSITION.  
NO APPARENT SIGNS OF TEST ACTIVITY, MISSILES, OR MISSILE-RELATED EQUIPMENT OBSERVED.

PERM MUNITIONS - CHEMICAL CMR K KIROV 98 UR 5758N 05554E [REDACTED]  
A NEW PROBABLE DOUBLE BASE CASTING BUILDING IS IN THE MID-STAGE OF CONSTRUCTION SW OF THE NITROGLYCERIN PRODUCTION AREA. NO INDICATIONS OF RECENT TEST ACTIVITY OBSERVED. NO MISSILES OR MISSILE-RELATED EQUIPMENT OBSERVED.

YASASHNAYA TASHLA PROB MSL ASSOCIATED FAC UR 5352N 04826E [REDACTED]

#### SECTION # 16

THE FUNCTION OF THE INSTALLATION CANNOT BE DETERMINED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

KUYBYSHEV ABM/PROB LR SAM SEARCH AREA UR 5313N 05014E [REDACTED]  
NO ABM/PROBABLE LONG RANGE SAM LAUNCH COMPLEXES OBSERVED IN CLOUD-FREE AREAS.

MINSK ABM/PROB LR SAM SEARCH AREA UR 5353N 02734E [REDACTED]  
NO ABM OR NEW PROBABLE LONG RANGE SAM COMPLEXES OBSERVED IN CLOUD-FREE PORTIONS.

25X1  
25X1

25X1  
25X1

25X1  
25X1

25X1  
25X1

25X1  
25X1

25X1  
25X1

25X1

CHELYABINSK ABM/PROB LR SAM SEARCH AREA UR 5510N 06125E [ ]  
NO ABM OR NEW PROBABLE LONG RANGE SAM COMPLEXES  
OBSERVED IN CLOUD-FREE AREAS.

25X1

KOMAROV SUSPECT MISSILE SEARCH AREA UR 4716N 04115E [ ]  
NO SSM SITE OBSERVED.

25X1

25X1

DONETSK ABM SEARCH UR 4888N 03747E [ ]  
NO MOSKVA-TYPE ABM ACTIVITY OBSERVED.

25X1

25X1

SVERDLOVSK ABM SEARCH UR 5650N 06035E [ ]  
NO MOSKVA-TYPE ABM ACTIVITY OBSERVED IN CLOUD-FREE  
AREAS.

25X1

ROSTOV ABM/PROB LONG RANGE SAM SEARCH UR 4714N 03942E [ ]  
NO MOSKVA-TYPE ABM OR NEW PROBABLE LONG RANGE SAM-  
RELATED FACILITIES OBSERVED.  
THE PREVIOUSLY IDENTIFIED ROSTOV PROBABLE LONG RANGE  
SAM LAUNCH COMPLEX IS CLOUD COVERED.

25X1

25X1

DNEPROPETROVSK ABM SEARCH UR 4828N 03502E [ ]  
NO MOSKVA-TYPE ABM COMPLEXES OBSERVED IN CLOUD-FREE  
AREAS.

25X1

25X1

KIYEV ABM SEARCH UR 5027N 03038E [ ]  
NO ABM LAUNCH COMPLEXES OBSERVED IN CLOUD-FREE AREAS.

25X1

25X1

GORKIY ABM SEARCH UR 5615N 04355E [ ]  
NO MOSKVA-TYPE ABM ACTIVITY IDENTIFIED IN CLOUD-FREE  
AREAS.

25X1

AMDERMA HEN HOUSE SEARCH UR 6945N 06139E [ ]  
NO EVIDENCE OF HEN HOUSE CONSTRUCTION IS IDENTIFIED IN  
CLOUD-FREE AREAS.

25X1

25X1

PORTION OF SEARCH AREA - PROBABLE

VORKUTA HEN HOUSE SEARCH UR 6738N 06480E [REDACTED]  
NO EVIDENCE OF HEN HOUSE CONSTRUCTION OBSERVED IN  
CLOUD-FREE AREAS.

25X1  
25X1

NIKOLAYEVSK HEN HOUSE SEARCH UR 5308N 14040E [REDACTED]  
NO EVIDENCE OF HEN HOUSE ACTIVITY IN PORTION OF SEARCH  
AREA OBSERVED.

25X1  
25X1

IVANOVO ABM/PROB LONG RANGE SAM SEARCH UR 5708N 04050E [REDACTED]  
NO ABM OR PROBABLE LONG RANGE COMPLEXES OBSERVED IN  
CLOUD-FREE AREAS.

25X1  
25X1

SOCHI ABM/PROB LONG RANGE SAM SEARCH UR 4335N 03945E [REDACTED]  
NO ABM/PROBABLE LONG RANGE SAM LAUNCH COMPLEXES  
OBSERVED IN CLOUD-FREE AREAS.

25X1  
25X1

SECTION # 17

KALININGRAD ABM/PROB LONG RANGE SAM SEARCH UR 5445N 02030E [REDACTED]  
NO ABM OR NEW PROBABLE LONG RANGE SAM LAUNCH COMPLEXES  
OBSERVED IN CLOUD-FREE AREAS.

25X1  
25X1

BAKU ABM/PROB LONG RANGE SAM SEARCH UR 4027N 04953E [REDACTED]  
NO ABM/PROBABLE LONG RANGE SAM LAUNCH COMPLEXES  
IDENTIFIED.

25X1  
25X1

OLENEGORSK AMM/PROB LONG RANGE SAM SEARCH UR 6808N 03318E [REDACTED]  
NO ABM/PROBABLE LONG RANGE SAM COMPLEXES IDENTIFIED IN  
CLOUD-FREE AREAS.

25X1  
25X1

MURMANSK ABM/PROB LONG RANGE SAM SEARCH UR 6858N 03305E [REDACTED]  
NO ABM/PROBABLE LONG RANGE SAM COMPLEXES OBSERVED IN  
CLOUD-FREE AREAS.

25X1  
25X1

YAKUTSK HEN HOUSE SEARCH UR 6205N 12944E [REDACTED]  
NO EVIDENCE OF HEN HOUSE CONSTRUCTION IDENTIFIED IN  
CLOUD-FREE AREAS.

25X1  
25X1

TUAPSE PROB LONG RANGE SAM SEARCH UR 4405N 03905E [REDACTED]  
NO PROBABLE LONG RANGE SAM ACTIVITY OBSERVED IN  
CLOUD-FREE AREAS.

25X1  
25X1

ZAPOROZHYE PROB LONG RANGE SAM SEARCH UR 4758N 03508E [REDACTED]  
NO PROBABLE LONG RANGE SAM ACTIVITY OBSERVED IN  
CLOUD-FREE AREAS.

25X1  
25X1

SARATOV PROB LONG RANGE SAM SEARCH UR 5132N 04680E [ ]  
NO PROBABLE LONG RANGE SAM ACTIVITY OBSERVED IN  
CLOUD-FREE AREAS.

25X1

KAMYSHIN PROB LONG RANGE SAM SEARCH UR 5005N 04525E [ ]  
NO PROBABLE LONG RANGE SAM ACTIVITY IDENTIFIED IN  
CLOUD-FREE AREAS.

25X1

POTI PROB LONG RANGE SAM SEARCH UR 4208N 04140E [ ]  
NO PROBABLE LONG RANGE SAM ACTIVITY OBSERVED.

25X1

GUBA LITSA SUBMARINE BASES NORTH - SOUTH UR 6926N 03224E [ ]  
OB -- AT LEAST 11 UNIDENTIFIED SS AND 7 UNIDENTIFIED  
SURFACE VESSELS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

GUBA LITSA NAVAL MISSILE STORAGE UR 6923N 03226E [ ]  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW  
CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY  
UNREPORTED FEATURES OBSERVED.

25X1

GUBA ANDREEVA NUCLEAR SUB SUPPORT FACILITY UR 6926N 03221E [ ]  
OB -- 4 UNIDENTIFIED SURFACE VESSELS AT PIERS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

GUBA MOTKA NAVAL BASE UR 6942N 03207E [ ]  
NO SUBMARINES OR EVIDENCE OF SUBMARINE FACILITIES  
OBSERVED.

25X1

PECHENGA NAVAL BASE LINAKHAMARI UR 6938N 03122E [ ]  
OB -- 8 UNIDENTIFIED SS AND 3 POSSIBLE AS AT THE  
SUBMARINE WHARVES AND 14 PROBABLE MS/PC MOORED IN THE  
INNER BAY.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

KRONSHTADT NAVAL BASE AND SHIPYARD UR 5959N 02946E [ ]  
OB -- AT LEAST 4 SS, 2 DD, AND 16 SMALL COMBATANTS IN  
THE SUBMARINE BASIN, 5 DD, 2 DE, 1 CA, 1 CL, 7 SMALL  
COMBATANTS, 1 AUXILIARY, AND 7 UNIDENTIFIED SMALL CRAFT  
IN THE CENTRAL HARBOR, AND 2 SMALL VESSELS AND 1 LARGE  
MERCHANT SHIP IN DRYDOCK IN THE CENTRAL HARBOR. ONE SS  
IS UNDERWAY OUTSIDE THE HARBOR.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR

25X1

SECTION # 18

PREVIOUSLY UNREPORTED FEATURES OBSERVED.

PLESETSK PROB LONG RANGE SAM LAUNCH CPLX UR 6312N 84189E [REDACTED]  
CONSTRUCTION STATUS OF FACILITIES AND PRESENCE OF  
MISSILES OR MISSILE-RELATED EQUIPMENT IS UNDETERMINED.

25X1

MOZHAYSK PROB LONG RANGE SAM LAUNCH CPLX UR 5538N 83548E [REDACTED]  
A MISSILE-HANDLING FACILITY IS IN AN EARLY STAGE OF  
CONSTRUCTION WEST OF LAUNCH SITE C. SERVICE ROADS FOR  
THE FACILITY HAVE BEEN UNDER CONSTRUCTION SINCE MISSION  
[REDACTED] TREE REMOVAL AND GROUND PREPARATION ARE  
UNDERWAY FOR COMPONENTS OF THE FACILITY.  
STATUS OF LAUNCH SITE CONSTRUCTION IS UNDETERMINED. NO  
MISSILES OR MISSILE-RELATED EQUIPMENT ARE IDENTIFIABLE.  
THE PREVIOUSLY REPORTED PROBABLE AIR WARNING RADAR  
FACILITY 3.5 NM SE OF THE LAUNCH COMPLEX IS NOW  
CONFIRMED. THE FACILITY IS IN THE MID-STAGE OF  
CONSTRUCTION.

25X1

25X1

25X1

KRASNOYARSK PROB LONG RANGE SAM LCH CPLX UR 5634N 89320E [REDACTED]  
SINCE THE LAST COVERAGE OF [REDACTED]  
CONSTRUCTION OF TRACK BEDS HAS BEEN INITIATED AT THE  
LAUNCH POSITIONS OF SITES A AND C AND POSSIBLY AT  
POSITIONS 4, 5, AND 6 OF SITE B. CONSTRUCTION ACTIVITY  
CONTINUES AT THE SUPPORT FACILITY AND IS NOW UNDERWAY  
AT THE MISSILE-HANDLING FACILITY. A DITCH/ROAD IS  
NEWLY OBSERVED EXTENDING FROM THE SUPPORT FACILITY A  
SHORT DISTANCE TO THE WEST OF THE COMPLEX. NO MISSILES  
OR MISSILE-RELATED EQUIPMENT ARE OBSERVED AT THE  
COMPLEX.

25X1

25X1

SHARYA PROB LONG RANGE SAM LAUNCH COMPLEX UR 5826N 84530E [REDACTED]  
CONSTRUCTION OF LAUNCH POSITION REVETMENTS HAS BEGUN  
SINCE [REDACTED] AT THE 3 LAUNCH SITES, WITH  
SITE A BEING MOST ADVANCED. NEW ROAD CONSTRUCTION,  
PROBABLY FOR THE MISSILE-HANDLING FACILITY, IS  
UNDERWAY. BUILDING CONSTRUCTION HAS PROGRESSED ON 2 OF  
THE 4 BUILDINGS AT THE SUPPORT FACILITY. NO  
SIGNIFICANT CHANGE IS OBSERVED IN THE STATUS OF THE  
TRACKING/GUIDANCE FACILITY. THE COMPLEX IS ESTIMATED  
TO BE IN AN EARLY-TO-MID STAGE OF CONSTRUCTION. NO  
MISSILES OR MISSILE-RELATED EQUIPMENT ARE IDENTIFIABLE.

25X1

25X1

NEYA PROB LONG RANGE SAM LAUNCH COMPLEX UR 5822N 84348E [REDACTED]  
AT LAUNCH SITE A, 2 ADDITIONAL LAUNCH REVETMENTS ARE  
UNDER CONSTRUCTION MAKING A TOTAL OF 6 LAUNCH  
POSITIONS.

25X1

POSITIONS, WHILE AT LAUNCH SITE C, 6 LAUNCH POSITION REVETMENTS ARE UNDER CONSTRUCTION. CLEARING OF TREES HAS BEGUN IN THE CENTER OF LAUNCH SITE B. IN THE SUPPORT AREA, A FOURTH BUILDING HAS BEEN CONSTRUCTED. NO MISSILES OR MISSILE-HANDLING EQUIPMENT OBSERVED.

MOSKVA PROB LONG RANGE SAM LCH POSITION UR 5520N 03627E [REDACTED] 25X1  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

TIKHVIN PROB LONG RANGE SAM LAUNCH CPLX UR 5944N 03324E [REDACTED] 25X1  
CONSTRUCTION HAS CONTINUED SINCE [REDACTED] 25X1  
[REDACTED] WITH COMMENCEMENT OF CONSTRUCTION ON LAUNCH SITES B AND C. NO MISSILES OR MISSILE-HANDLING EQUIPMENT OBSERVED.

MINSK PROB LONG RANGE SAM LCH CPLX UR 5335N 02710E [REDACTED] 25X1  
23 NM SW OF MINSK.  
CONSTRUCTION CONTINUES SINCE [REDACTED] 25X1  
THREE LAUNCH SITES ARE NOW VERY DISTINCT AND CLEARINGS HAVE BEEN CUT IN THE VICINITY OF THE TRACKING/GUIDANCE FACILITY. THE LAUNCH AREA MAIN ROAD, LAUNCH SITE ACCESS ROAD, AND THE LAUNCH SITE SERVICE ROADS ARE VIRTUALLY COMPLETE. CLEARING AND LEVELING OPERATIONS ARE UNDERWAY AT THE LAUNCH POSITIONS AT ALL 3 SITES. EARTH SCARS/CLEARINGS EXTEND FROM THE LAUNCH POINTS AT ALL 3 SITES, WITH THOSE AT SITE B EXTENDING AWAY FROM THE SITE AT AN UNUSUAL ANGLE. CLEARING AND ROAD CONSTRUCTION ACTIVITY IS APPARENT IN THE CONTROL CENTER OF EACH LAUNCH SITE. NO EVIDENCE OF CONSTRUCTION AT THE MISSILE-HANDLING FACILITY, THE SUPPORT AREA, OR THE AIR WARNING RADAR FACILITY OBSERVED.

SECTION # 19

[REDACTED] 25X1  
[REDACTED] 25X1  
STARYY KILDIN CRUISE-MISSILE LAUNCH SITE 1 UR 6922N 03413E [REDACTED] 25X1  
EACH LAUNCH POSITION IS OCCUPIED BY AN UNIDENTIFIED PIECE OF EQUIPMENT. OCCUPANCY OF THE GUIDANCE AREA IS UNDETERMINED. NO OTHER SIGNIFICANT ACTIVITY OBSERVED.

[REDACTED] 25X1  
[REDACTED] 25X1  
STARYY KILDIN CRUISE-MISSILE LAUNCH SITE 2 UR 6922N 03484E [REDACTED] 25X1  
BOTH LAUNCH POSITIONS APPEAR TO BE OCCUPIED BY UNIDENTIFIED EQUIPMENT. OCCUPANCY OF THE GUIDANCE AREA IS UNDETERMINED. NO OTHER SIGNIFICANT ACTIVITY OBSERVED.

STARYY KILDIN CRUISE-MISSILE LAUNCH SITE 3 UR 6921N 03481E [REDACTED]  
BOTH LAUNCH POSITIONS APPEAR TO BE OCCUPIED BY UNIDENTIFIED EQUIPMENT. OCCUPANCY OF THE GUIDANCE AREA IS UNDETERMINED. NO OTHER SIGNIFICANT ACTIVITY OBSERVED.

25X1

POTI CRUISE-MISSILE LAUNCH SITE 1 UR 4210N 04139E [REDACTED]  
BOTH LAUNCH POSITIONS APPEAR TO BE OCCUPIED. NO OTHER SIGNIFICANT ACTIVITY OBSERVED.

25X1

POTI CRUISE-MISSILE LAUNCH SITE 2 UR 4206N 04140E [REDACTED]  
ONE LAUNCH POSITION IS POSSIBLY OCCUPIED. OCCUPANCY OF THE OTHER LAUNCH POSITION IS UNDETERMINED. NO OTHER SIGNIFICANT ACTIVITY OBSERVED.

25X1

POTI CRUISE-MISSILE LAUNCH SITE 3 UR 4211N 04139E [REDACTED]  
OCCUPANCY OF THE LAUNCH POSITIONS IS UNDETERMINED. NO OTHER SIGNIFICANT ACTIVITY OBSERVED.

25X1

JUN 19 MYS KEKURSKII CRUISE-MISSILE LAUNCH SITE UR 6953N 03209E [REDACTED]  
ON [REDACTED] OCCUPANCY OF THE LAUNCH POSITIONS AND GUIDANCE AREA IS UNDETERMINED.  
ON [REDACTED] EACH LAUNCH POSITION IS OCCUPIED BY 2 UNIDENTIFIED OBJECTS. NO OTHER ACTIVITY OBSERVED.

25X1

MYS KEKURSKII CRUISE-MISSILE SUPPORT FAC UR 6953N 03209E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

25X1

BATUMI CRUISE-MISSILE LAUNCH SITES UR 4136N 04135E [REDACTED]  
NO CRUISE-MISSILE SITES OR ASSOCIATED CRUISE-MISSILE ACTIVITY OBSERVED WITHIN A 3-NM RADIUS OF THE REFERENCED COORDINATES.

25X1

SUPSA CRUISE-MISSILE LAUNCH SITE UR 4158N 04147E [REDACTED]  
SITE IS PROBABLY UNOCCUPIED. NO NEW CONSTRUCTION ACTIVITY OBSERVED.

25X1

GLAZOV REGIONAL MILITARY STOR INSTLN UR 5751N 05316E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

NOVAYA MEZINOVKA IRBM REAR DEPOT UR 5338N 02655E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

25X1

MOSKVA SAM STORAGE SITE 4 UR 5519N 03727E [REDACTED]  
NO NON-SA-1 TYPE MISSILES OR ASSOCIATED EQUIPMENT CAN

25X1

BE IDENTIFIED WITHIN THE SITE.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

MOSKVA SAM STORAGE SITE 6 UR 5551N 03651E [REDACTED]  
NO NON-SA-1-TYPE MISSILES OR ASSOCIATED EQUIPMENT CAN  
BE IDENTIFIED WITHIN THE SITE.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
[REDACTED]

25X1

#### SECTION # 20

KORDON SAM TRAINING CENTER UR 4725N 04803E [REDACTED]  
THE ENTIRE SAM TRAINING CENTER IS CLOUD COVERED WITH  
THE EXCEPTION OF THE HOUSING AND SUPPORT AREA, THE AREA  
TO THE NW OF THE HOUSING AND SUPPORT AREA IN THE  
VICINITY OF LAUNCH SITES 13A AND 13B QNEWLY IDENTIFIED  
ON [REDACTED] AND THE LANDING STRIP. NO  
APPARENT CHANGE IS OBSERVED AT THE HOUSING AND SUPPORT  
AREA SINCE [REDACTED] UNIDENTIFIED  
VEHICULAR/EQUIPMENT ACTIVITY IS APPARENT IN THE  
VICINITY OF LAUNCH SITES 13A AND 13B. A  
RECTANGULAR-SHAPED GROUND SCAR OUTLINE APPROXIMATELY  
THE SAME WIDTH AS THE LANDING STRIP IS OBSERVED  
EXTENDING FROM EACH END OF THE LANDING STRIP. ALTHOUGH  
NO GROUND SCARRING IS OBSERVED WITHIN THE OUTLINE  
PATTERN, THIS OUTLINE MAY REPRESENT THE INITIAL  
SURVEYING STAGE FOR LENGTHENING THE STRIP. NO MISSILES  
OR MISSILE-RELATED EQUIPMENT IDENTIFIED IN CLOUD-FREE  
PORTIONS OF THE SAM TRAINING CENTER.

25X1

AIR FACILITIES  
HA-ERH-PIN AIRCRAFT ENG PLT PING-FANG-TIEN CH 4535N 12639E [REDACTED]  
SEE HA-ERH-PIN/PING-FANG-TIEN AIRFIELD, [REDACTED]  
FOR AIRCRAFT. NO EVIDENCE OF CURRENT PRODUCTION  
OBSERVED.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1  
25X1

25X1

NAVAL ACTIVITY/PORTS

MAYANG-DO SUBMARINE BASE KN 3959N 12812E [REDACTED]  
OB -- 1 MEDIUM SS IN GRAVING DOCK AND 1 MEDIUM SS AT  
EAST INLET PIER.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

CHING-TAO SUBMARINE BASE CH 3684N 12819E [REDACTED]  
OB -- AT LEAST 5 UNIDENTIFIED SS AT FINGER PIERS,  
NUMEROUS UNIDENTIFIED VESSELS AT QUAYS, AND 1 DD, 1  
DD/DE, 3 POSSIBLE LST, AND 8 SMALLER UNIDENTIFIED  
VESSELS AT LARGE PIER. SMALL SCALE PRECLUDES FURTHER  
IDENTIFICATION.

25X1

25X1

CHING-TAO NAVAL DOCKYARD CH 3684N 12818E [REDACTED]  
OB -- NUMEROUS UNIDENTIFIED VESSELS AT PIERS AND IN  
GRAVING DOCK.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

CHIANG-KO-CHUANG NAVAL FACILITY CH 3686N 12832E [REDACTED]

25X1

25X1

OB -- 2 MEDIUM COMBATANTS, 7 UNIDENTIFIED SMALL CRAFT,  
AND 9 PROBABLE CARGO BARGES.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

PRIOZERSK MTB BASE SOUTHEAST UR 6058N 83028E [REDACTED]  
OB -- 3 PROBABLE SMALL VESSELS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

DOLGAYA NAVAL BASE UR 6915N 03350E [REDACTED]  
OB -- 1 DD, 4 DE, AND 17 SMALL VESSELS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

ARKHANGELSK NAVAL OPERATING BASE UR 6434N 84030E [REDACTED]  
OB -- 5 UNIDENTIFIED SMALL VESSELS AT QUAY.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

LENINGRAD SHIPYARD SUDOMEKH 196 UR 5955N 03016E [REDACTED]  
OB -- AT LEAST 3 UNIDENTIFIED VESSELS AT QUAYS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

LENINGRAD SHIPYARD ZHDANOV 198 UR 5952N 03013E [REDACTED]  
OB -- 3 PROBABLE KRESTA DLGM MEDITERRANEAN-MOORED TO  
THE QUAY, 1 PROBABLE DDG, 3 UNIDENTIFIED VESSELS, AND 3  
MERCHANT SHIPS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

LENINGRAD SHIPYARD ADMIRALTY 194 UR 5955N 03016E [REDACTED]  
OB -- 1 LARGE AND 6 SMALL VESSELS AT QUAYS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

LENINGRAD SHIPYARD BALTYSK 189 UR 5955N 03015E [REDACTED]  
OB -- 1 UNIDENTIFIED VESSEL IN THE LAUNCHING BASIN, 1  
LARGE AND 1 MEDIUM MERCHANT VESSELS AT THE QUAY, AND 1  
LARGE UNIDENTIFIED VESSEL ON THE WAYS.  
MOST OF THE YARD IS CLOUD COVERED.

25X1

NIKOLAYEVSK SHIPYARD UR 5308N 14044E [REDACTED]  
OB -- 4 UNIDENTIFIED VESSELS AT PIERS, 3 UNIDENTIFIED  
VESSELS IN GRAVING DOCK, AND 4 UNIDENTIFIED OBJECTS ON  
BUILDING WAYS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

CONSTANTA NAVAL BASE RU 4409N 02839E [REDACTED] 25X1  
OB -- [REDACTED] -- SEVERAL UNIDENTIFIED VESSELS ALONG MOLE.  
[REDACTED] -- 9 UNIDENTIFIED SURFACE VESSELS.  
NO EVIDENCE OF SUBMARINE ACTIVITY OBSERVED.

MANGALIA NAVAL BASE AND HQ RUMANIAN NAVY RU 4348N 02832E [REDACTED] 25X1  
OB -- [REDACTED] -- AT LEAST 9 UNIDENTIFIED SMALL SURFACE  
VESSELS.  
NO EVIDENCE OF SUBMARINE ACTIVITY OBSERVED.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

BAUTINO PORT FACILITIES UR 4432N 05816E [REDACTED] 25X1  
OB -- 2 SMALL POSSIBLE COMBATANTS, 6 MERCHANT SHIPS, 1  
FLOATING DOCK, AND NUMEROUS SERVICE/SMALL CRAFT.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

MOSKALVO PORT FACILITIES UR 5334N 14230E [REDACTED] 25X1  
OB -- 2 TANKERS AT QUAY, 1 BULK CARGO SHIP IN ROAD,  
AND 1 LARGE BARGE MOORED OFFSHORE IN COMPANY WITH A  
POSSIBLE DREDGE.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

1 Break

SECTION # 22

LING-SHAN-WEI MTB BASE CH 3555N 12809E [REDACTED]  
OB -- 2 POSSIBLE VESSELS AT PIER.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

BARU NAVAL BASE UR 4828N 04950E [REDACTED]  
OB -- AT PIERS -- 1 DE, 1 POSSIBLE DE, 1 POSSIBLE PF, 8  
PC, 7 SC, 7 PROBABLE LCU, 8 MSF, 1 PROBABLE MP-6, 2  
SMALL UNIDENTIFIED COMBATANTS, 2 UNIDENTIFIED  
AUXILIARIES, AND SEVERAL SMALL CRAFT/SUPPORT VESSELS.  
IN BASIN -- 2 PROBABLE PC, 1 MSF, 2 LSM, AND NUMEROUS  
SMALL VESSELS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

BRAILA PORT FACILITIES RU 4517N 02759E [REDACTED]  
NUMEROUS VESSELS ARE OBSERVED ALONG THE BANKS OF THE  
DANUBE. SMALL SCALE PRECLUDES FURTHER INTERPRETATION.

25X1

ELECTRONICS/COMMUNICATIONS  
NARO-FOMINSK PROB ABM PHASED-ARRAY RADAR UR 5529N 03641E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

PUMMANKI PROB COASTAL DEFENSE RADAR FAC UR 6946N 03145E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

NAN-CHING RADAR PLANT 728 CH 3205N 11845E [REDACTED]  
NO NEW CONSTRUCTION OR CHANGES IN FACILITIES OBSERVED.

25X1

SARY-SHAGAN R - D RADAR FACILITY 1 UR 4600N 07339E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

25X1

SARY-SHAGAN R - D RADAR FACILITY 2 UR 4556N 87338E [REDACTED]  
WORK CONTINUES ON THE RADAR ANTENNA AT HEN ROOST SOUTH.  
MANY OF THE CRATES OBSERVED ON [REDACTED]  
JUST EAST AND WEST OF THE ANTENNA SITE AT HEN ROOST  
SOUTH HAVE BEEN REMOVED. IN THE AREA BETWEEN THE  
CONTROL BUILDING AND THE NORTH END OF THE ANTENNA,  
CONSTRUCTION APPEARS TO CONSIST OF FOOTINGS, POSSIBLY  
FOR A NEW CONTROL BUILDING. THE BUILDING OBSERVED  
UNDER CONSTRUCTION SINCE [REDACTED] IN THE SE CORNER  
OF THE SUPPORT AREA APPEARS ALMOST EXTERNALLY COMPLETE.  
THE 3 SUSPECT ANTENNAS OBSERVED UNDER CONSTRUCTION IN  
THE AREA JUST SOUTH OF THE SUPPORT AREA CAN BE  
IDENTIFIED ONLY.

25X1  
25X1

SARY-SHAGAN TRACKING FACILITY 11 UR 4641N 87238E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

SARY-SHAGAN TRACKING FACILITY 2 UR 4558N 87335E [REDACTED]  
NO SIGNIFICANT CHANGES OBSERVED SINCE [REDACTED]  
[REDACTED] IN CONSTRUCTION ACTIVITY PREVIOUSLY  
OBSERVED IN THE AREA JUST NE OF THE [REDACTED]  
DOME. TWO SMALL STRUCTURES HAVE APPEARED SINCE MISSION  
[REDACTED] CLOSE TO THE EAST AND 3 CLOSE TO THE WEST SIDE OF  
THE LARGE TRIAD BUILDING.

25X1  
25X1  
25X1  
25X1  
25X1  
25X1

SARY-SHAGAN TRACKING FACILITY 3 UR 4538N 87236E [REDACTED]

25X1

#### SECTION # 23

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

SARY-SHAGAN TRACKING FACILITY 4 UR 4557N 87213E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

25X1  
25X1

SARY-SHAGAN TRACKING FACILITY 5 UR 4554N 87128E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

25X1

SARY-SHAGAN TRACKING FACILITY 6 UR 4655N 87858E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

25X1

SARY-SHAGAN TRACKING FACILITY 9 UR 4653N 87152E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

25X1

SARY-SHAGAN TRACKING FACILITY 10 UR 4657N 87232E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

SARY-SHAGAN TRACKING FACILITY 12 UR 4624N 87234E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

NAN-CHING POSSIBLE RADIO ASTRONOMY FAC CH 3283N 11847E [REDACTED]  
NO MILLS CROSS-TYPE RADAR OBSERVED.

25X1

HAI-MEN SUSPECT COMMUNICATIONS SITE CH 3288N 12110E [REDACTED]  
NO COMMUNICATIONS SITE OBSERVED.

25X1

MILITARY ACTIVITY  
AYTOS ARMY BARRACKS 1 BU 4242N 82714E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

BURGAS ARMY BARRACKS 15 BU 4231N 82727E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

GORNA ORYAKHOVITSA ARMY BARRACKS 1/2/3 BU 4387N 82542E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KOLAROVRAD ARMY BARRACKS NORTHEAST 2/3 BU 4316N 82655E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

NOVA ZAGORA ARMY BARRACKS NORTH 1 BU 4238N 82688E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

25X1

AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

RAZGRAD ARMY BARRACKS WEST 1 BU 4331N 02630E [REDACTED]  
WESTERN SECTOR OF RAZGRAD.  
INSTALLATION CONTAINS 3 BARRACKS, 1 BARRACKS/ADMINISTRATION BUILDING, 1 VEHICLE STORAGE BUILDING, 3 LARGE PROBABLE STORAGE BUILDINGS, 8 STORAGE BUILDINGS, 7 SMALL POSSIBLE STORAGE BUILDINGS, AND 3 SUPPORT BUILDINGS.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

YAMBOL ARMY BARRACKS 1 AND 4 BU 4229N 02631E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

TOLBUKHIN ARMY BARRACKS WEST 1 BU 4334N 02748E [REDACTED]

25X1  
25X1

#### SECTION # 24

NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

TURGOVISHTE ARMY BARRACKS 1 BU 4314N 02633E [REDACTED]  
SMALL SCALE PRECLUDES IDENTIFICATION.  
TURNOVO ARMY BARRACKS 2 BU 4384N 02538E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

VARNA ARMY BARRACKS SOUTHEAST BU 4310N 02755E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

CHEN-CHIANG ARMY BARRACKS CHU-TZU-KANG CH 3204N 11917E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

CHEN-CHIANG ARMY BARRACKS SHIH-TOU-KANG SW CH 3209N 11921E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

CHEN-CHIANG ARMY BARRACKS WEST CH 3211N 11924E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

CHENG-YANG MILITARY COMPLEX CH 3619N 12022E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

TANG-YUAN MILITARY BARRACKS AREA CH 4645N 12955E [REDACTED]  
THE PARADE FIELD APPARENTLY IS BEING RESURFACED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

WEI-FANG ARMY BARRACKS WEST-SOUTHWEST CH 3641N 11983F [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

WEI-FANG BARRACKS 1 CH 3648N 11857E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

CHANG-LO ARMY BARRACKS AL 6 CH 3638N 11853E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

NAGYATAD HO BARRACKS 3 HU 4613N 01721E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

HUEYANG HEADQUARTERS ARMY GROUP KN 3842N 12736E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

HAMHUNG BARRACKS - AAA DEFENSES KN 3959N 12738E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

YANGDOG-UP MILITARY COMPLEX KN 3913N 12638E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

25X1

SECTION # 25

BIRLAJ ARMY BARRACKS SOUTH 1/2 RU 4612N 82739E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

BASARABI ARMY BARRACKS 1 RU 4411N 82825E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

25X1

BRAILA ARMY BARRACKS EAST CENTRAL RU 4516N 82758E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

25X1

BUCURESTI ARMORED TRAINING CENTER RU 4426N 82606E [REDACTED]  
INSTALLATION CANNOT BE IDENTIFIED IN THE URBAN AREA.

25X1

BUCURESTI ARMY BARRACKS CENTRAL SOUTHWEST RU 4425N 82605E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

BUCURESTI ARMY BARRACKS SOUTHEAST 62/63 RU 4423N 82608E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

BUCURESTI ARMY BARRACKS SOUTHWEST 6 RU 4425N 82603E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

BUCURESTI ORDNANCE DEPOT CHITILA 1/2 RU 4429N 82559E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

BUZAU ARMY BARRACKS 6 RU 4589N 82647E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

FOCSANI ARMY BKS S 1/2 - AMMO DUMP SOUTH RU 4541N 82710E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

IASI ARMY BARRACKS 2 RU 4789N 82738E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

IASI ARMY BARRACKS NORTHWEST RU 4718N 82734E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

MEDGIDIA ARMY BARRACKS 2 RU 4415N 82815E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

MEDGIDIA ARMY BARRACKS 1 RU 4414N 82816E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

PIATRA NEAMT ARMY BARRACKS 1 RU 4655N 82624E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

RIMNICU SARAT ARMY BARRACKS - STOR DEPOT RU 4524N 82783E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

25X1

#### SECTION # 26

SFINTU GHEORGHE ARMY BARRACKS 1 RU 4552N 82548E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

TECUCI ARMY BARRACKS 1 RU 4551N 82724E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

TOPRAISAR ARMY BARRACKS 1 RU 4481N 82827E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

AKHALKALAKI ARMY BARRACKS AL 1 UR 4124N 84328E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

AKHALKALAKI MILITARY BARRACKS AL 2 UR 4123N 84329E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

AKHALTSIKHE ARMY BARRACKS SOUTH UR 4138N 84259E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

AKHALTSIKHE ARMY BARRACKS EAST AL 1 UR 4137N 84389E [REDACTED]  
IMMEDIATELY EAST OF AKHALTSIKHE.  
INSTALLATION CONTAINS AT LEAST 4 BARRACKS, 1  
ADMINISTRATION BUILDING, 3 VEHICLE STORAGE BUILDINGS,  
AND APPROXIMATELY 20 OTHER BUILDINGS.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

ALABINO ARMY BKS AND TRAINING CENTER AL 1 UR 5532N 83657E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

ARKHANGELSK ARMY BARRACKS ISAKOBORKA AL 2 UR 6425N 84039E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

BAKU ARMY BKS - DEPOT BALADZHARY AL 1 UR 4025N 84948E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

BAKU ARMY BARRACKS SHAUMYAN UR 4025N 84949E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

BAKU ARMY SUPPLY DEPOT KISHLY UR 4024N 84952E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

BAKU ARMY BARRACKS KOKI AL 11 UR 4024N 84942E [REDACTED]  
LOCATION OF A BARRACKS AREA AT THE REFERENCED  
COORDINATES WAS CONFIRMED ON [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

BAKU ARMY BARRACKS NORTHEAST AL 22 UR 4825N 04955E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

BALAKLEYA AMMO DEPOT NORTHEAST 65 DA 1 UR 4928N 03652E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

#### SECTION # 27

BANK ARMY BARRACKS AL 1 UR 3924N 04915E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

BANK ARMY TRAINING AREA UR 3925N 04917E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

BARANOVICHY ARMY BARRACKS EAST AL 2 UR 5307N 02602E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

BARANOVICHY ARMY BARRACKS SOUTHWEST AL 1 UR 5306N 02558E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

BARANOVICHY TRAINING AREA LESNAYA UR 5303N 02547E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

BATUMI ARMY BARRACKS EAST AL 1 UR 4138N 04141E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

BATUMI ARMY BARRACKS GOGOL AL 1 UR 4138N 84148E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR [REDACTED]  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

BATUMI ARMY BARRACKS WEST AL 2 UR 4138N 84137E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR [REDACTED]  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

BATUMI TANK/ASSAULT GUN RANGE 1 UR 4135N 84135E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR [REDACTED]  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

BATUMI ARMY BKS S AL 3 - BKS SSE - TNG A UR 4135N 84139E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR [REDACTED]  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

BAYRAM-ALI ARMY BARRACKS SOUTHEAST AL 1 UR 3736N 86218E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR [REDACTED]  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

BORISOV ARMY BARRACKS CENTRAL AL 4 UR 5413N 82831E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR [REDACTED]  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

BORISOV ARMY BARRACKS SOUTH AL 2 UR 5418N 82829E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

BORISOV ARMY BARRACKS WEST AL 1 UR 5413N 82828E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

BORISOV SUPPLY DEPOT - POL STORAGE AREA UR 5412N 82830E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR [REDACTED]

SECTION # 28

PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

BORISOV TRAINING AREA - RANGE WEST UR 5411N 82821E [REDACTED]  
OCCUPANCY OF HOUSING AND BIVOUAC AREAS CANNOT BE

DETERMINED. THE AREA APPEARS TO HAVE BEEN OCCUPIED  
RECENTLY.

BORISOV ARMY TRAINING AREA II UR 5488N 82829E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

DZERZHINSK ARMY BARRACKS SE STANKOVO AL 2 UR 5338N 82712E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1

GRODNO ARMY BARRACKS EAST AL 1 UR 5348N 82350E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

GRODNO ARMY BARRACKS AL 2 UR 5348N 82350E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

GRODNO ARMY BARRACKS LOSOSNA AL 3 UR 5348N 82346E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

GRODNO ARMY BARRACKS KELBASIN AL 6 UR 5338N 82346E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

VARDEYSK ARMY BARRACKS NORTHEAST AL 1 UR 5439N 82104E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

JONAVA ARMY BARRACKS SOUTHEAST AL 1 UR 5503N 82423E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

KAGUL ARMY BARRACKS AL 1 UR 4554N 82811E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

25X1

KAUNAS ARMY BARRACKS AIRFIELD NORTH AL 7 UR 5453N 02353E [ ]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

KAUNAS ARMY BARRACKS AND DEPOT AL 9 UR 5452N 02356E [ ]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

KAUNAS ARMY BARRACKS KIPRO AL 8 UR 5454N 02356E [ ]  
NO INDICATION OF CW STORAGE OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

KAUNAS ARMY BARRACKS SOUTH AL 1 UR 5452N 02356E [ ]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

KAUNAS MILITARY BARRACKS PAMOTERYS UR 5445N 02355E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KAZAN ARMY BARRACKS GORKI AL 1 UR 5545N 04989E [ ]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

#### SECTION # 29

AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

KAZAN ARMY BARRACKS SOUTHEAST AL 4 UR 5543N 04989E [ ]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

25X1

KEGICHEVKA ORDNANCE DEPOT SOUTHWEST DO 1 UR 4916N 03544E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

25X1

KILYAZI AMMUNITION DEPOT UR 4850N 04921E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

25X1

KOBRIN ARMY BARRACKS NORTHEAST AL 1 UR 5213N 02422E [ ]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

25X1

KOZELSK ARMY BARRACKS UR 5402N 03546E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KUBINKA ARMY BARRACKS AND MANEUVER AREA UR 5533N 03641E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KURSK ARMY BARRACKS NORTH UR 5146N 03611E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KURSK ARMY BARRACKS SOUTHWEST UR 5143N 03609E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KUTAISI AMMUNITION DEPOT SOUTH DA 1 UR 4210N 04244E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KUTAISI ARMY BARRACKS SOUTHEAST AL 2 UR 4214N 04243E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

KUTAISI ARMY BKS SOUTH RIONI RIVER AL 5 UR 4214N 04241E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KUTAISI MILITARY BARRACKS AL 4 UR 4215N 04257E [REDACTED]  
SMALL SCALE PRECLUDES CONFIRMATION OR NEGATION AS A  
MILITARY INSTALLATION. THIS AREA APPEARS TO BE A  
CONSTRUCTION CAMP FOR THE NEARBY DAM.

25X1

KUYBYSHEV ARMY BARRACKS AL 1 UR 5312N 05809E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

KUYBYSHEV ARMY BARRACKS POLYANA AL 7 UR 5314N 05812E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

KUYBYSHEV ARMY BARRACKS AL 4 UR 5314N 05014E [REDACTED] [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR

25X1  
25X1

SECTION # 38

PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

KUYBYSHEV ARMY BARRACKS KRYAZH AL 5 UR 5306N 05007E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

KUYBYSHEV MILITARY TRAINING AREA UR 5303N 05030E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

KUYBYSHEV MILITARY EQP AND VEHICLE PARK UR 5316N 05017E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

LIDA ARMY BARRACKS AL 1 UR 5353N 02516E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

LIDA ARMY BARRACKS EAST AL 3 UR 5353N 02524E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

LIDA ARMY BKS SE AL 2 AND TRAINING AREA SEUR 5345N 02528E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

LUKOV ARMY BARRACKS MATSEYEV AL 1 UR 5114N 02421E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

LOUSTARI ARMY BARRACKS EAST AL 2 UR 6926N 03109E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

LOUSTARI ARMY BARRACKS NORTH AL 4 UR 6929N 03108E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

LOUSTARI ARMY BARRACKS SOUTH AL 3 UR 6924N 03108E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

LYUBOML ARMY BARRACKS AL 1 UR 5112N 02402E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

LYUBOML ARMY TRAINING AREA WEST UR 5113N 02355E [REDACTED]  
OCCUPANCY IS UNDETERMINED. THE AREA APPEARS TO HAVE  
HAD NO RECENT ACTIVITY.

25X1

MARINA GORKA ARMY BARRACKS AL 1 UR 5330N 02810E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

MARINA GORKA TRAINING AREA 2 UR 5329N 02806E [REDACTED]  
OCCUPANCY OF HOUSING AND BIVOUAC AREAS AND EVIDENCE OF  
RECENT ACTIVITY CANNOT BE DETERMINED.

25X1

MARY ARMY BARRACKS AL 2 UR 3735N 06151E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

MARY ARMY BARRACKS MURGAB RIVER AL 3 UR 3735N 06151E [REDACTED]

25X1

SECTION # 31

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

MARY ARMY BARRACKS GOKCHA AL 1 UR 3736N 86151E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

MARY ARMY BARRACKS NORTH AL 4 UR 3736N 86151E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

PECHENGA MANEUVER AREA UR 6933N 03112E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

NARO-FOMINSK ARMY BARRACKS NORTH UR 5524N 03644E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

NASOSNYY ARMY BARRACKS AAA UR 4937N 04933E [REDACTED] 25X1  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

NESVIZH PROBABLE ARMY BARRACKS AL 1 UR 5313N 02641E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

NIKEL ARMY BARRACKS AKHMALAKHTI UR 6929N 03811E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

NIKOLAYEVSK ARMY BARRACKS NORTH AL 1 UR 5388N 14843E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

NIKOLAYEVSK ARMY SUPPLY DEPOT UR 5388N 14845E [REDACTED] 25X1  
INSTALLATION CANNOT BE CONFIRMED OR NEGATED.

NOVOCHEKASSY ARMY BKS SOUTHWEST AL 1 UR 4723N 04884E [REDACTED] 25X1  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

NOVOCHEKASSY ARMY BARRACKS PERSIANOVKA UR 4732N 04886E [REDACTED] 25X1  
0.5 NM ENE OF KRASYUKOVSKAYA, JUST WEST OF THE  
RAILROAD.  
INSTALLATION CONTAINS 1 BARRACKS, 1 PROBABLE BARRACKS,  
1 BARRACKS/ADMINISTRATION BUILDING, 1 U-SHAPED  
ADMINISTRATION BUILDING, 18 QUARTERS, 2 STORAGE

BUILDINGS, 2 VEHICLE STORAGE BUILDINGS, 1 BUILDING UNDER CONSTRUCTION, A DOUBLY SECURED STORAGE AREA WITH 2 PROBABLE WAREHOUSES AND 2 STORAGE BUILDINGS, AND ANOTHER SECURED AREA WITH A BUNKER.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
OCHAMCHIRE AAA FIRING RANGE UR 4237N 04131E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
OMSK TRAINING AREA 1 SOUTH UR 5451N 07322E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
OMSK ORDNANCE AND AMMUNITION DEPOT PUG UR 5508N 07324E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

SECTION # 32

25X1  
OMSK PROBABLE MILITARY AREA EAST UR 5455N 07327E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
OMSK PROBABLE ARMY BARRACKS AL 3 UR 5455N 07319E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
OMSK ARMY BARRACKS CENTRAL AL 2 UR 5458N 07323E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
OSIPOVICH AMMUNITION DEPOT EAST DA 1 UR 5318N 02848E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
OSIPOVICH ARMY BARRACKS NORTHEAST UR 5318N 02839E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

OSIPOVICH ARMY BARRACKS SOUTH AL 2 UR 5317N 02838E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

LAPICHI ARMY BARRACKS TSEL AL 2 UR 5324N 02828E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

OSIPOVICH MILITARY DEPOT SOUTHWEST DX 1 UR 5317N 02837E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

OSIPOVICH TRAINING AREA VEREYTSY UR 5317N 02829E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

OSIPOVICH ARMY TRAINING AREA 2 UR 5316N 02848E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

OSIPOVICH STORAGE AREA UR 5321N 02831E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

PECHENGA ARMY BARRACKS AL 3 UR 6933N 03113E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

PECHENGA ARMY BKS OZERO KAAKKURIN AL 1 UR 6931N 03119E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

PECHENGA ARMY BARRACKS SOUTH AL 4 UR 6932N 03112E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

PERM ARMY BARRACKS SOUTH AL 1 UR 5880N 05615E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

PERM ORDNANCE DEPOT UR 5750N 05615E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

GRODNO TRAINING AREA NORTH UR 5351N 02355E [REDACTED] 25X1  
THE AREA IS VERY ACTIVE.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

POSTAVY ARMY BARRACKS AL 3 UR 5587N 022648E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

POSTAVY ARMY BARRACKS EAST AL 2 UR 5587N 022653E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

PROZHANT ARMY BARRACKS SLOBODKA UR 5230N 02431E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

PYATIGORSK ARMY BARRACKS SOUTHEAST UR 4401N 04304E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

RATNO PROBABLE MILITARY INSTALLATION UR 5140N 02432E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

ROSTOV ARMY BARRACKS NORTH AL 1 UR 4715N 03942E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

ROSTOV SIGNAL OCS UR 4715N 03941E [REDACTED] 25X1  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

SERGEYEVKA ARMY BARRACKS AL 1 UR 4419N 13148E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

SERPUKHOV ORDNANCE DEPOT 45 UR 5455N 03724E [REDACTED]  
OCCUPANCY IS UNDETERMINED.  
NO SIGNIFICANT CHANGE OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

LUGANSK TRAINING AREA 1 SLAVYANO SERBSK UR 4846N 03857E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

SLONIM ARMY BARRACKS SSE AL 2 UR 5304N 02519E [REDACTED]  
THE ROAD PREVIOUSLY REPORTED AS UNDER CONSTRUCTION  
APPEARS COMPLETE.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

SLONIM ARMY TRAINING AREA SOUTHEAST UR 5303N 02524E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

SYZRAN ENGR - ORDNANCE DEPOT RR STN EAST UR 5310N 04828E [REDACTED]  
SMALL SCALE PRECLUDES READOUT OF OPEN AND COVERED  
STORAGE FACILITIES.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

SECTION # 34

TATARSK ARMY BARRACKS AL 1 UR 5512N 07559E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1

TULA ARMY BARRACKS KOSTROVO AL 6 UR 5423N 03729E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR

25X1

PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

TULA ARTILLERY OCS UR 5418N 03735E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

TULA MILITARY TRAINING AREA UR 5415N 03734E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

TYUMEN TRAINING AREA TA 1 UR 5775N 06545E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

UKMGERE ARMY BARRACKS AL 1 UR 5514N 02443E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

ULYANOVSK ARMY BARRACKS AL 3 UR 5419N 04823E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1  
25X1

ULYANOVSK ARMY BKS OCS AL 2 - SIGNAL OCS UR 5428N 04824E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

MEREFA ARMY BARRACKS AL 1 UR 4947N 03559E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

CHI-LIN ARMY BARRACKS AREA NNW CH 4353N 12631E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

CHI-LIN ARMY BARRACKS SOUTHWEST CH 4349N 12628E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

CHI-LIN AF TRAINING SCHOOL CH 4347N 12633E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1  
25X1

CHI-LIN ARMY BARRACKS NORTHWEST CH 4356N 12628E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

PEI-SHAN-CHENG-CHEN ARMY BKS EAST AL 2 CH 4223N 12528E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF TROOP OR SUPPLY BUILDUP OBSERVED.

25X1  
25X1

SECTION # 35  
PEI-SHAN-CHENG-CHEN ARMY BKS WEST AL 1 CH 4228N 12528E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO INDICATION OF TROOP OR SUPPLY BUILDUP OBSERVED.

25X1  
25X1

HA-ERH-PIN ARMY BARRACKS SOUTHEAST CH 4539N 12643E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

CHING-TAO BARRACKS AREAS CH 3608N 12229E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

HAI-LUNG ARMY BARRACKS CH 4231N 12548E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

OTAR MILITARY BARRACKS NORTH AL 1 UR 4334N 07512E [ ]  
OB -- APPROXIMATELY 150 PROBABLE VEHICLES/PIECES OF  
EQUIPMENT.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

YESSENTUKI MILITARY BARRACKS AL 1 UR 4483N 04253E [ ]

25X1  
25X1

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

TUNG-FENG PROBABLE MILITARY CAMP CH 4242N 12532E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

PAN-SHIH ARMY BARRACKS EAST CH 4255N 12684E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

LIAO-YUAN HQ 46 INF DIV - BKS EAST AL 1 CH 4254N 12589E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

CHU-CHEN ARMY BARRACKS SE AL 2 CH 3456N 11818E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

CHU-CHEN ARMY BARRACKS AL 1 CH 3458N 11816E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

NAKHABINO ENGINEER BARRACKS AL 1 UR 5558N 03718E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

TEDZHEN ARMY BARRACKS AL 1 UR 3721N 06032E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

TERMEZ ARMY BARRACKS AL 1 UR 3713N 06716E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

SECTION # 36

FOU-NING ARMY BARRACKS CH 3347N 11947E [REDACTED]  
WEST EDGE OF FOU-NING.  
AREA CONTAINS 8 POSSIBLE BARRACKS, 1 ADMINISTRATION  
BUILDING, AND 2 VEHICLE/STORAGE BUILDINGS.  
NO INDICATION OF MILITARY ACTIVITY OBSERVED.

25X1

TAI-SHAN ARMY BARRACKS NORTHWEST AL 1 CH 3418N 11914F [REDACTED]  
LOCATION OF BARRACKS AREA AT THE REFERENCED COORDINATES  
WAS CONFIRMED AND A DESCRIPTION WAS GIVEN ON MISSION

25X1

[REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
AREA APPEARS OCCUPIED AND ALL PORTIONS APPEAR ACTIVE.

25X1

YU-SHU-TUN ARMY BARRACKS EAST CH 4789N 12354E [REDACTED]  
SMALL SCALE PRECLUDES CONFIRMATION OR NEGATION OF  
MILITARY ASSOCIATION.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

MIHAEL KOGALNICEANU ARMY BARRACKS 1 RU 4421N 02828E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

AN-TUNG-WEI ARMY BARRACKS AL 1 CH 3510N 11918E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

CHI-MO MILITARY AREA CH 3623N 12035E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

CHIAO-NAN HQ 201 INFANTRY DIVISION CH 3552N 11959E [REDACTED]  
AREA DOES NOT APPEAR TO HAVE ANY SIGNATURES WHICH WOULD  
INDICATE MILITARY ACTIVITY OR OPERATIONS.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

CHIAO-NAN ARMY BARRACKS AL 3 CH 3552N 11955E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

CHIAO-NAN ARMY BARRACKS AL 2 CH 3557N 12000E [REDACTED]

25X1

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

HSIN-CHUAN ARMY BARRACKS AL 1 CH 3558N 12089E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

HAI-LUNG ARMY BARRACKS WEST AL 1 CH 4239N 12549E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

JIH-CHAO ARMY BARRACKS CH 3525N 11925E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

BAKU ARMY BARRACKS AL 16 UR 4028N 04935E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

BRYANSK ORDNANCE DEPOT BRYANSK II UR 5313N 03423E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

ZHUKOVKA AMMUNITION DEPOT SERGINO SOUTH UR 5688N 09143E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

SECTION # 37

NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

ADADYM AMMUNITION DEPOT NAZAROVY UR 5589N 09017E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

KUAN-NAN ARMY BARRACKS AL 1 CH 3485N 11928E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

25X1

SSU-YANG ARMY BARRACKS AL 1 CH 3342N 11841E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

LIEN-SHUI ARMY BARRACKS NE AL 1 CH 3346N 11916E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

HSI-PA ARMY BARRACKS NW AL 1 CH 3338N 11988E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

HSIANG-SHUI-KOU ARMY BKS AL 1 CH 3412N 11932E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

SHE-YANG ARMY BARRACKS SW AL 1 CH 3348N 12017E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

WANG-TAI ARMY BARRACKS SOUTH AL 1 CH 3601N 11958E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1  
25X1

WANG-TAI ARMY BARRACKS SE AL 2 CH 3603N 12001E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

OSIPOVICH TACTICAL SSM SUPPORT FAC DM-1 UR 5319N 02848E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

KILYAZI TACTICAL SSM SUPPORT FAC DM-1 UR 4849N 04920E [ ]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

MARY TACTICAL SSM SUPPORT FACILITY DM-1 UR 3734N 06147E [ ]  
CONSTRUCTION CONTINUES ON THE WARHEAD STORAGE BUNKER.

25X1

NO OTHER NEW CONSTRUCTION OR CHANGES IN THE FACILITY  
OBSERVED.

KOVOVOI TACTICAL SSM SUPPORT FACILITY UR 6014N 83827E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

ZAVITINSK TACTICAL SSM SUPPORT FACILITY UR 5809N 12927E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

CHI-CHI-HA-ERH COMPLEX CH 4728N 12357E [REDACTED]  
INDUSTRIAL ACTIVITY APPEARS LIGHT TO MODERATE.

#### SECTION # 38

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

CHI-LIN COMPLEX CH 4351N 12634E [REDACTED]  
INDUSTRIAL ACTIVITY APPEARS MODERATE.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

CHIA-MU-SSU COMPLEX CH 4648N 13022E [REDACTED]  
ON [REDACTED] SMOKE IS RISING FROM THE PULP/PAPER MILL  
AND THERMAL POWERPLANT AREA, APPROXIMATELY 15 RIVER  
BOATS ARE AT THE PORT FACILITIES OR NEARBY IN THE  
RIVER, AND THE RAIL YARD IS APPROXIMATELY 25 PERCENT  
ILLED, INDICATING A NORMAL LEVEL OF INDUSTRIAL  
ACTIVITY.

NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

FU-LA-ERH-CHI COMPLEX CH 4712N 12338E [REDACTED]  
INDUSTRIAL ACTIVITY APPEARS LIGHT TO MODERATE.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

SUNCHON COMPLEX KN 3925N 12556E [REDACTED]  
INDUSTRIAL ACTIVITY APPEARS LIGHT.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

KAECHON COMPLEX KN 3941N 12553E [REDACTED]

25X1  
25X1

INDUSTRIAL ACTIVITY APPEARS LIGHT.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

SA-ERH-TU REFINERY AND OIL FIELD COMPLEX CH 4636N 12501E [REDACTED]  
THE OIL FIELDS WITH AT LEAST 400 WELLS OR EXPLORATION  
DRILLINGS COVER AN AREA OF APPROXIMATELY 600 SQ NM.  
THE REFINERY APPEARS COMPLETE. THE THERMAL POWERPLANT  
DOES NOT APPEAR TO BE OPERATING.

25X1  
25X1

CHIAO-HO COMPLEX CH 4342N 12719E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

MU-LENG-CHEN COMPLEX CH 4432N 13814E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

KOSUNG COMPLEX KN 3844N 12611E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR  
PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1  
25X1

GRODNO RAILROAD STATION YARDS - SHOPS UR 5341N 02351E [REDACTED]  
THE RAIL YARD IS APPROXIMATELY 15 PERCENT FILLED.

25X1  
25X1

KOVEL RR YARDS SHOPS - TRANSFER SITES UR 5114N 02441E [REDACTED]  
THE RAIL YARDS ARE APPROXIMATELY 28 PERCENT FILLED.

25X1  
25X1

LENINGRAD RR STN YARDS AND SHOPS MOSKVA UR 5954N 03022E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

25X1  
25X1

LENINGRAD RR STN YARDS - SHOPS FINLANDIY UR 5957N 03021E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

25X1  
25X1

LENINGRAD RR STATION AND YARDS VARSHAVKIY UR 5953N 03018E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

25X1  
25X1

BREST RR TRANSLOADING YARD TSENTRALNYY UR 5206N 02341E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

25X1  
25X1

BREST RR TRANSLOADING YARD WEST UR 5205N 02339E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

25X1  
25X1

BREST RR TRANSLOADING YARD MUKHAVETS UR 5205N 02340E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

SECTION # 39

LENINGRAD RR CLF YARDS - SHOPS OKTYABR UR 5952N 03025E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

25X1  
25X1

LENINGRAD RR CLF YARDS SHUSHARY UR 5947N 03024E [REDACTED]  
POOR INTERPRETABILITY PRECLUDES IDENTIFICATION OF RAIL CARS.

25X1  
25X1

LENINGRAD RR CLF YARDS SREDNE-ROGATSKAYA UR 5949N 03017E [REDACTED]  
THE LEVEL OF ACTIVITY CANNOT BE DETERMINED.

25X1  
25X1

ZHABINKA RAILROAD STATION AND YARDS UR 5212N 02401E [REDACTED]  
THE RAIL YARDS ARE APPROXIMATELY 15 TO 20 PERCENT FILLED.

25X1  
25X1

IZHEVSK ARMS - MACHINE EQUIP PLANT 71 - 74UR 5650N 05311E [REDACTED]  
CONSTRUCTION APPEARS COMPLETE ON THE BUILDING AT THE WEST EDGE OF THE PLANT. NO UNREPORTED FEATURES, MISSILES, MISSILE COMPONENTS, OR LARGE RAIL CARS ARE DISCERNIBLE.

25X1  
25X1

VOTKINSK ARMS MACHINE AND STEEL PLT 235 UR 5703N 05359E [REDACTED]  
NO LARGE RAIL CARS OBSERVED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

CHAPAYEVSK EXPLOS - MUN LDG CMB 389 - 15 UR 5258N 04943E [REDACTED]  
NO SIGNIFICANT CHANGE OBSERVED.

25X1

ULYANOVSK MOTOR VEHICLE PLANT UR 5418N 04820E [REDACTED]  
NO MISSILE-HANDLING OR MISSILE-RELATED GROUND SUPPORT EQUIPMENT OR VEHICLES OBSERVED.

25X1  
25X1

NAN-CHING ARMS - AMMUNITION PLANT 387 CH 3201N 11847E [REDACTED]  
NO VEHICLES, WEAPONS, OR EQUIPMENT ARE DISCERNIBLE. NO INDICATION OF ACTIVITY OBSERVED AT THE FIRING RANGE. NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

25X1

KUTAISI MOTOR VEHICLE PLANT UR 4215N 04237E [REDACTED]  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.

25X1

WEST NICHOLSON/SOUTH AFRICA POS RAIL LINE RZ 2104S 02922E [REDACTED] 25X1  
NO EVIDENCE OF RAILROAD CONSTRUCTION OBSERVED.

LENINGRAD ARM - TANK PLT BOLSHEVIK 232 UR 5952N 03028E [REDACTED] 25X1  
PRODUCTION AREAS AND TYPES OF PRODUCTION CANNOT BE IDENTIFIED.  
NO MISSILES, MISSILE-RELATED EQUIPMENT, NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

CHI-CHI-HA-ERH ARMS - AMMO PLANT 127 CH 4719N 12358E [REDACTED] 25X1  
NO VEHICLES, WEAPONS, OR EQUIPMENT OBSERVED.  
NO NEW CONSTRUCTION, CHANGES IN FACILITIES, OR PREVIOUSLY UNREPORTED FEATURES OBSERVED.

TASHTAGOL MINING ACTIVITY UR 5239N 08751E NO COMRX ACTIVITY IN THIS AREA CONSISTS OF EXPLORATORY DRILLING AND TRENCHING AND A VERY SMALL SPOIL PILE FROM A PROBABLE VERTICAL SHAFT. SECURED AREA PREVIOUSLY REPORTED IS FOR STORAGE OF BLASTING SUPPLIES. THERE IS ALSO EXTENSIVE PLACER MINING IN THE STREAM BEDS JUST WEST OF THE AREA.

OTHER ACTIVITY NEFTEKAMSK POSS CHEMICAL FERTILIZER PLANT UR 5606N 05415E [REDACTED] 25X1  
CONSTRUCTION CONTINUES IN THE NORTH-CENTRAL PORTION OF THE PLANT. NO EVIDENCE OBSERVED TO CONFIRM THE FUNCTION OF THIS INSTALLATION. NO VEHICLES/PIECES OF

SECTION # 48

EQUIPMENT ARE DISCERNIBLE.

BULYZHINO SENSITIVE OPERATIONS COMPLEX UR 5615N 02819E [REDACTED] 25X1  
NO SIGNIFICANT CHANGE OBSERVED.